



簡 福 星 啤 呀 工 廠 KAN FOOK SING MOTOR WORKSHOP

61 Oulu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 8858 2128, 8858 4361

Fax: (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221888-00E

GST Reg. No. M90005335-E

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A300356875MKC	Date of Loss:	08/07/2022
Vehicle Reg. No.:	YK3288M	Driveable?	
Driver Age/Info:	64	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HOCK WAH CONSTRUCTION & ENTERPRISE PTE LTD	Contact No:	+6587577458
Driver:	NG CHEN HWEI		
Make/Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Vehicle Reg. Date:	23/10/2013
Vehicle Colour:	WHITE		
Engine No:	4HK1981726	Chassis No:	JAANPR75HC7103585
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO GIA		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	1,214.40
Miscellaneous Items	50.00
Labour	530.00
Paintwork Labour	450.00
Towing	0.00
Calculated Gross Total (S\$)	2,244.40
- Excess (S\$)	600.00
(S\$)	1,644.40
+ GST 7.00% (S\$)	115.11
Nett Amount (S\$)	1,759.51

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Jul 2022)

Parts: N/A ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	<i>fn ✓</i> *370.00 F
2	1		*FRONT BUMPER BRACKET RH	0.00	0.00	<i>?</i> *90.00 F
3	1		*FRONT BUMPER BRACKET LH	0.00	0.00	<i>?</i> *90.00 F
4	1		*FRONT GRILLE	0.00	0.00	<i>ag ✓</i> *305.00 F
5	6		*FRONT GRILLE CLIP	0.00	0.00	<i>ul ✓</i> *24.00 F
6	1		*HEADLAMP RH	0.00	0.00	<i>X</i> *225.00 F

F=Franchise part.

Sub Total (S\$)	1,104.00
+ Margin on L,N Items 10.00% (S\$)	110.40
Total Parts (S\$)	1,214.40

Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT NUMBER PLATE

50.00

Sub Total (S\$)

50
61

50.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New

300

450.00

Labour Items

2 TO CHECK WIRING SYSTEM

New

30

50.00

3 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New

300

480.00

Gross Labour Cost (S\$)

980.00

Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749

WP' 22/7/22 @ 1020

Resurvey before paint

2 days

Not authorised

Ex \$600

Taufik @ khant.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: