

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 12 Jul 2022)
Parts: N/A ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	fn ✓ *370.00 F 140
2	1		*FRONT BUMPER BRACKET RH	0.00	0.00	bt ✓ ? *90.00 F 65
3	1		*FRONT BUMPER BRACKET LH	0.00	0.00	bt ✓ ? *90.00 F 65
4	1		*FRONT GRILLE	0.00	0.00	anw ✓ *305.00 F
5	6		*FRONT GRILLE CLIP	0.00	0.00	nl ✓ *24.00 F 20
6	1		*HEADLAMP RH	0.00	0.00	nn X *225.00 F
franchise part.						
Sub Total (\$\$)						1,104.00
+ Margin on L,N Items 10.00% (\$\$)						110.40
Total Parts (\$\$)						1,214.40

Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT NUMBER PLATE

50.00

Sub Total (S\$) 64- 50.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New 300 450.00

Labour Items

2 TO CHECK WIRING SYSTEM

New 30 50.00

3 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New 300 480.00

Gross Labour Cost (S\$) 980.00

Kan Fook Sing Motor Workshop/YK3288M/12/07/2022 17:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfu 97495749

WP' 22/7/22 E1020

Resumy before paint

2 days

Tanfu e-Claims.com