

ASS. REC. BY:

REF:

AIG / 22006963 / Kc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STV 671D Yr Regn: 02/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 150706 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AU1 1110880Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 20/7/22

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 25/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/8 21 Lm 826001 Cntrl 1/9/22

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #09-16,
AIG Building, Singapore 079120

Estimate bill : TT 23 / 22 / TP / WT

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Registration No : SJV671D
Make model : Honda Vezel

*Not with work
11 Sep @ 2600h
Resurvey After Paint
4. days*

Mileage : Date : 22 / 07 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SJR2909C AND SJV671D
ALONG BALESTIER ROAD ON 20 JULY 2022 AT ABOUT 1250HRS.**

1pc	Rear boot	<i>PA 953</i>	\$	<i>BU</i>	1,565.00	✓
1pc	Rear boot 'Vezel' designation		\$	<i>BU</i>	76.00	✓
2pcs	Rear boot damper		(Each \$230.00)	\$	<i>BU</i>	460.00 X
1pc	Rear boot rubber		\$	<i>BU</i>	122.00	X
2pcs	Rear fender wheel arch		(Each \$135.00)	\$	<i>BU</i>	270.00 X
1pc	Rear LH tail lamp (Outer)		\$	<i>BU</i>	675.00	X
1pc	Rear end panel	<i>875.30</i>	\$	<i>BU</i>	724.00	✓
1pc	Rear bumper		\$	<i>BU</i>	513.00	✓
2pcs	Rear bumper side cover (LH)		\$	<i>BU</i>	176.00	✓
1pc	Rear bumper reflector (LH)		\$	<i>CM</i>	122.00	✓
2pcs	Rear bumper side retainer		(Each \$33.00)	\$	<i>BU</i>	66.00 X
Sub total :			\$		4,769.00	
Less 20% discount :			\$		953.80	
A total :			\$		3,815.20	

Special net items :

1set	Rear bumper parktronic sensor kit		\$	<i>BU</i>	280.00	<i>2005N</i>
B total :			\$		280.00	
Remove and refit rear windscreen.			\$		250.00	<i>1201</i>
Total amount for Page : 1			\$		4,345.20	

Tropical Tech Automobile Services

(Signature)
(Authorised Signature)
William Tan

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #09-16,
AIG Building, Singapore 079120

Estimate bill : TT 23 / 22 / TP / WT

Registration No : SJV671D

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Make model : Honda Vezel

Mileage :

Date :

22 / 07 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SJR2909C AND SJV671D
ALONG BALESTIER ROAD ON 20 JULY 2022 AT ABOUT 1250HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot 'Vezel' designation, rear boot dampers, rear boot rubber, rear fender wheel archs, rear LH tail lamp (Outer), rear bumper, rear bumper side cover (LH), rear bumper parktronic sensor kits, rear bumper reflector (LH), rear bumper side retainers.

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear end panel, ~~rear bumper~~, rear bumper side cover (LH), rear bumper parktronic sensor kit.

Balance amount brought from Page 1 :

Grand final amount :

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

\$	900.00	600
\$	100.00	50
\$	80.00	20
\$	200.00	30
\$	1,200.00	320
\$	4,345.20	
\$	6,825.20	