



Your Ref : SNM22D204973/C01

Date: 26th September 2022

Our Ref : CS/CTI22006976/Kqy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKJ 6717T
ACCIDENT ON 15/07/2022**

Instruction was received to inspect the vehicle Reg. No. SKJ 6717T. The inspection was conducted on 22/07/2022 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd, 160 Sin Ming Drive #04-01/02 Sing Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: SKJ 6717T
Make/Model	: Mercedes Benz B 200 AT ABS Airbags HID 2WD 5DR(Chrome)
Year of Registration	: 2013
Body Colour	: Metallic Black
Chassis Number	: WDD2462432J134854
Engine Capacity	: 1595 cc

The vehicle sustained damages at the front portion and undercarriage. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 23,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 13,744.00)
Nett Liability	<u>S\$ 9,256.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.