

源摩哆廠

# GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

## REPAIR ESTIMATE FOR SLM8837P

No.	Qty	List Items	
1	1	Rear bumper <i>1381</i>	<i>CPT</i> \$ 1,400.20 ✓
2	1	Rear bumper reverse sensor	\$ <i>sn</i> 509.10 X
3	1	Rear bumper lower spoiler <i>482.50</i>	<i>Net</i> \$ <i>sn</i> 645.10 ✓
4	1	Rear bumper LH reflector	\$ <i>sn</i> 66.10 ✓
5	1	Rear bumper LH side retainer	\$ <i>Dr's</i> 110.35 ✓
6	1 set	Rear bumper clips	\$ <i>sn</i> 50.00 ✓
7	1	Rear bumper inner foam	\$ <i>CPT</i> 110.45 ✓
8	1	Rear bumper inner reinforcement	\$ <i>n</i> 518.00 X
			\$ 3,409.30
			Less 25% \$ 852.33
			Total : \$ 2,556.98

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 700.00 <i>200h</i>
2	To putty and spray Spray Paintings charges.	\$ 800.00 <i>220h</i>
3	To check wirings and lightings.	\$ 40.00 <i>10h</i>
4	To remove, refit & reset reverses sensors.	\$ 80.00 <i>50h</i>
5	To supply and apply anti rust treatment	\$ <i>nn</i> 60.00 X
		Total : \$ 1,680.00

Total Parts and Labour : \$ 4,236.98

*Not Authorised*

*Re survey Repair*

*3 days*

*@ 2130.30*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: