

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 18 Nov 2022

Preliminary Advice

Insured Vehicle No : GBC2376M

TP Vehicle No : SKG3221S

Make : BMW 520I

Date of Inspection : 22/07/2022

Inspection At : XINHUA WORKSHOP - KAKI BUKIT (HQ)
23 KAKI BUKIT AVENUE 4, #04-01 (SOUTH WING)
SINGAPORE 415933

Accident Date : 11/07/2022

Assignment Date : 22/07/2022

Est. Duration of Repair : 5 DAYS

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,318.13
Revised Amount	:S\$	8,355.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,355.92
Lump Sum Repair	:S\$	6,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.