

XIN HUA WORKSHOP PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SKG3221S

Vehicle Model : BMW 520I

Accident Date : 11.07.2022

Original Reg Date : 31.05.2012

Date : 21.07.2022

Chassis : WBAXG12090DX49317

TP Ins. MSIG

TP MSIG.

Celine.

1	1 pc	Front Bumper <i>new</i>		1,548.90	✓
2	1 pc	Front Bumper Side Retainers <i>new</i>		98.60	+
3	1 pc	Front Bumper Top Rubber		78.20	+
4	1 pc	Front Bumper Reinforcement <i>2 new</i>		650.00	+
5	1 pc	Front Bumper Reinforcement Bracket	119.00	238.00	+
6	1 pc	Front Bumper Sponge <i>new</i>		195.80	+
7	1 pc	Front Bumper Lower Grille <i>2 new</i>		185.60	+
8	1 pc	Front Bumper Fog Lamps		260.80	+
9	1 pc	Front Bumper Fog Lamps Cover <i>2</i>		98.50	+
10	1 pc	Front Bumper Spray Nozzle Motor <i>new</i>	142.00	145.80	+
11	1 pc	Front Bumper Spray Nozzle Cover <i>new</i>	50.00	58.30	+
12	2 pcs	Front Bumper Sensor (Original)	345.00	690.00	+
13	2 pcs	Front Bumper Sensor Holder	35.80	71.60	+
14	1 pc	Front Grille <i>new</i>		168.90	+
15	1 pc	Headlamp <i>cracked</i>		2,458.90	✓
16	1 pc	Headlamps Bottom Retainers <i>new</i>		85.20	+
17	1 pc	Support Panel <i>new</i>		685.90	+
18	1 pc	Front fender <i>Dented.</i>		925.70	✓
19	1 pc	Front fender signal indicator <i>Dented</i>		145.80	✓
20	1 pc	Front fender inner cowling <i>new</i>		245.80	✓
21	1 pc	Side mirror Assy <i>new</i>		845.20	+
22	1 pc	Front door RH <i>Dented.</i>		1,548.60	✓
23	1 pc	Front door inner trim <i>new</i>		698.70	+
24	1 pc	Front sideskirt Rh <i>new</i>		725.80	+
25	1 pc	Front Bonnet <i>new</i>		1,985.60	+
26	1 pc	Front Rim <i>new</i> <i>125. led</i>		1,256.90	+

subtotal 16,097.10

parts disc 10% 5% 14,487.39

1pc wiper washer Tank ~~\$292.4~~ *led*1pc Front Fender bracket RH \$112.8 *Best* ✓

7111.50

6755.92

Special Nett

1	1 set	Front fender inner cowling clips <i>new</i>		30.00	✓
2	1 set	Front bumper clips <i>new</i>		30.00	✓
3	1 set	Front Grille clips <i>new</i>		30.00	x
4	1 set	Headlamp Clips <i>new</i>		30.00	x
5	1 pc	Front Number Plate with Cover <i>new</i>		70.00	x

Labour charge

Panel Beating		2,000.00	700
Spray painting		2,000.00	700
Check Wiring on headlamp		120.00	30.
Anti rust		180.00	60.
Remove and install front sensor.		150.00	50

1540

total \$ 19,127.39

Adrian Lj
h/s 22/07/22.

total: 8355.92
h/s: 6.6k
05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6.6k