

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5595B

Vehicle No.:

Chassis No.:

Co UEN: enable repair.

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 JUL 2022

- | | PART |
|---|-------------------------------------|
| 1 | COVER, REAR BUMPER |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |
| 1 | COVER, REAR BUMPER, LOWER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | RETAINER, REAR BUMPER SIDE, LH |
| 1 | RETAINER, REAR BUMPER SIDE, RH |
| 1 | FILLER, REAR BUMPER EXTENSION, RH |
| 1 | FILLER, REAR BUMPER EXTENSION, LH |
| 1 | COVER, FLOOR UNDER, NO.1 LH |
| 1 | COVER, FLOOR UNDER, NO.2 RH |
| 1 | COVER, REAR FLOOR CTR |
| 1 | COVER, DECK TRIM, REAR |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK |

SHD5595B

JTDKB3FU403074003

200303878K

TOYOTA

PRIUS

12/05/2022

PC3891U/ China.

26/10/2018

LIST		
\$	R 442.60	X
\$	R 332.70	X
\$	Sn 15.40	X
\$	Red/Est 576.30	
\$	R 116.50	}
\$	Sn 117.70	
\$	R 123.70	
\$	Sn 123.70	
\$	Sn 175.10	
\$	Sn 241.90	
\$	Sn 229.90	
\$	Sn 126.70	
\$	R 650.30	
TOTAL	\$ 3,272.50	
25%	\$ 818.13	
	\$ 2,454.38	

Special Nett

- | | | | |
|-------------------------------------|-----------|-----------------|------|
| 1SET PARKING AID | \$ | Sn 700.00 | X |
| 1SET REAR BUMPER CLIP | \$ | nn 95.00 | X |
| 1 REAR TAILGATE STICKER "Trans-Cab" | \$ | nn 80.00 | X |
| 1 REAR TAILGATE STICKER "6555-3333" | \$ | nn 80.00 | X |
| 1 REAR BUMPER ADVERTISEMENT | \$ | Sn 100.00 | born |
| 1 REAR BUMPER PROTECTOR | \$ | nn 180.00 | X |
| 1SET REAR BUMPER RETAINER CLIP | \$ | nn 85.00 | X |
| 1 END PANEL TRIM CLIP | \$ | nn 65.00 | X |
| TOTAL | \$ | 1,285.00 | |

TOTAL PARTS \$ 3,739.38

LABOUR (PART-BY-PART) Repair Days

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	100%
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↪	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	↪	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	↪	480.00	X
To check steering geometry and computer wheel alignment	\$	↪	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	↪	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	na	2,200.00	X
To reinstall rear bumper parking sensor.	\$	↪	170.00	X
To Check Electrical Lighting Concerned.	\$	↪	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	↪	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	↪	220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	↪	380.00	X
TOTAL	\$		7,910.00	