

ASS. REC. BY:

REF:

C72/22006990/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH05341S Yr Regn: 91, 19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy P.R.V. c.c. 1798Colour M.P. White / Red A/C: Insured / Std / NI / NASp. Reading 378705 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU 003 078775Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: Wanli 195/65R15
R: SailunBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 27/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body
The UIC / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 21/7/2022

Date / Time Action / Instruction

22/7/21 Lmp @ 2850h Cadet

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Notified
L1 Sing & 2850p

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5341S

Vehicle No.:

Chassis No.:

Co UEN:

21 JUL 2022

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD5341S

JTDKB3FU003078775

200303878K

TOYOTA

PRIUS

27/04/2022

SLV60T/CHINA

11/01/2019

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,300.70 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	193.50 X
1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	\$	17.90 X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	231.30 X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	110.60 ✓
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	97.50 X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	13.30 ✓
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	43.50 ✓
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	26.30 ✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	926.00
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	238.30
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,294.90
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	193.50
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	\$	17.90
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	87.10
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	98.90
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	21.90
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	34.90
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	15.40
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	926.00
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	206.70
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80
1	RIM	\$	1,900.10
1	FENDER SUB-ASSY, FRONT LH	\$	977.80 ✓

Trans-cab Auto Services Pte Ltd**AAD2204-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5341S

1 LINER, FRONT FENDER, LH	\$	<i>pu</i>	202.50	X
1 PANEL SUB-ASSY, QUARTER, LH	\$	<i>n</i>	871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$	<i>n</i>	139.80	X

TOTAL \$ 12,121.90**25% \$ 3,030.48****\$ 9,091.43****Special Nett**

1 FENDER CLIP	\$	<i>nn</i>	65.00	X
1 FENDER LINER CLIP	\$	<i>nn</i>	65.00	X
1 FENDER CLIP	\$	<i>nn</i>	65.00	X
1 FENDER LINER CLIP	\$	<i>nn</i>	65.00	X
1 TYRE	\$	<i>pu</i>	350.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	<i>nn</i>	65.00	X
1 FRT DOOR ADVERTISEMENT	\$	<i>ndllwa</i>	200.00	<i>120sn</i>
1 RR DOOR ADVERTISEMENT	\$	<i>n</i>	200.00	<i>120sn</i>
1 FRT DOOR STICKER TRANSCAB	\$	<i>nn</i>	100.00	<i>60sn</i>
1 REAR DOOR STICKER TEL. NO	\$	<i>nn</i>	100.00	<i>60sn</i>
1SET CLIP, ROCKER PANEL MOULDING	\$	<i>nn</i>	65.00	X
TOTAL	\$		1,340.00	

TOTAL PARTS \$ 10,431.43**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *500*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *880*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *60*

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5341S

To Check Electrical Lighting Concerned.

	\$	170.00	<i>201</i>
TOTAL	\$	3,590.00	

Over All Total	\$	14,021.43
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~20~~ days*4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: