

*Not Authorised
Pulney B4 paint*

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHC5899E

Q 1201.58

AAD2207-

22 JUL 2022

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC5899E
JTDKB3FU903092027
200303878K
TOYOTA
PRIUS GEN 4
21/07/2022
SKC4177B/AUTOGEN
30/09/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>cm</i> 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i> 332.70 ✗
1	GUARD, REAR BUMPER, CENTER	\$	<i>ndm</i> 374.50 ✓
1	SEAL, REAR BUMPER SIDE, RH	\$	<i>sn</i> 118.30 ✗
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>sn</i> 132.60 ✗
1	COVER, REAR BUMPER, LOWER	\$	<i>at</i> 22.00 ✓
1	COVER, DECK TRIM, REAR	\$	<i>sn</i> 126.70 ✗
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>h</i> 651.00 ✗
1	REFLECTOR ASSY, REFLEX, RH	\$	<i>sn</i> 39.00 ✗
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	<i>sn</i> 339.60 ✗
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	<i>sn</i> 261.00 ✗
1	COVER, REAR COMBINATION LAMP, RH	\$	<i>sn</i> 69.90 ✗
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>n</i> 1,147.80 ✗
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>na</i> 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>na</i> 54.60 ✗
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>na</i> 47.90 ✗
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>sn</i> 913.60 ✗
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>sn</i> 259.20 ✗
1	WEATHERSTRIP, BACK DOOR	\$	<i>sn</i> 372.30 ✗
1	STAY ASSY, BACK DOOR, LH	\$	<i>sn</i> 242.50 ✗
1	STAY ASSY, BACK DOOR, RH	\$	<i>sn</i> 242.50 ✗
1	HINGE ASSY, BACK DOOR, LH	\$	<i>sn</i> 61.00 ✗
1	HINGE ASSY, BACK DOOR, RH	\$	<i>sn</i> 61.00 ✗
TOTAL		\$	6,409.90
25%		\$	1,602.48
		\$	4,807.43

Special Nett

REAR BUMPER SIDE CLIP \$ *na* 60.00 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5899E**AAD2207-**

1 BOOT STICKER TRANSCAB	\$	na	100.00	X
1 BOOT STICKER TEL NO	\$	na	100.00	X
1SET PARKING AID	\$	na	700.00	X
1SET REAR BUMPER CLIP	\$	na	85.00	X
1 REAR BUMPER RETAINER CLIP	\$	na	75.00	X
TOTAL	\$		1,120.00	
TOTAL PARTS	\$		5,927.43	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	2201
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	101
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	na	170.00	X
TOTAL	\$		5,100.00	

Over All Total \$ 11,027.43**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART) Repair Days**20 Days****2 days****Acknowledged by Repairer****Signature:****Date:**