

ASS. REC. BY:

REF:

Kenneth

22006991KV

ASSIGNMENT

PHC 58992

From:

Date:

Estimated Cost:

Veh No:

Yr Regn:

09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c.

1798

Colour

M.F. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

152610

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J7DKB3FU903092027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inopder / Jammed / Leaked / Burnt or

Brake: Inopder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSN / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.


Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1.B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1. GIA not ready

25/7/22

B1201-58 (red 9825.85, 89%)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / I.B.I. (\$ 1201.58)

HORN

RADIATOR

32

Not Authoised
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5899E

AAD2207-

2201.58

22 JUL 2022

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC5899E
JTDKB3FU903092027
200303878K
TOYOTA
PRIUS GEN 4
21/07/2022
SKC4177B/AUTOGEN
30/09/2020

PART		LIST	
1	COVER, REAR BUMPER	\$ CM	485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ R	332.70 X
1	GUARD, REAR BUMPER, CENTER	\$ Pd	374.50 ✓
1	SEAL, REAR BUMPER SIDE, RH	\$ R	118.30 X
1	RETAINER, REAR BUMPER SIDE, RH	\$ R	132.60 X
1	COVER, REAR BUMPER, LOWER	\$ G	22.00 ✓
1	COVER, DECK TRIM, REAR	\$ R	126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ R	651.00 X
1	REFLECTOR ASSY, REFLEX, RH	\$ R	39.00 X
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$ R	339.60 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$ R	261.00 X
1	COVER, REAR COMBINATION LAMP, RH	\$ R	69.90 X
1	PANEL SUB-ASSY, BACK DOOR	\$ R	1,147.80 X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ R	54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$ R	54.60 X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$ R	47.90 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ R	913.60 X
1	BOARD ASSY, BACK DOOR TRIM	\$ R	259.20 X
1	WEATHERSTRIP, BACK DOOR	\$ R	372.30 X
1	STAY ASSY, BACK DOOR, LH	\$ R	242.50 X
1	STAY ASSY, BACK DOOR, RH	\$ R	242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$ R	61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$ R	61.00 X
TOTAL		\$	6,409.90
25%		\$	1,602.48
		\$	4,807.43

Special Nett

1 REAR BUMPER SIDE CLIP \$ R 60.00 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5899E**AAD2207-**

1 BOOT STICKER TRANSCAB	\$	nn	100.00	X
1 BOOT STICKER TEL NO	\$	nn	100.00	X
1SET PARKING AID	\$	nn	700.00	X
1SET REAR BUMPER CLIP	\$	nn	85.00	X
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00	X

TOTAL \$ 1,120.00**TOTAL PARTS \$ 5,927.43****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	2201
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	101
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X

TOTAL \$ 5,100.00**Over All Total \$ 11,027.43****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:****(PART-BY-PART) Repair Days****20 Days****2 days**