

TP ALG
Xiao Long

SKG 1527Z. 2018 March.

BMW 530i 1998cc

WBAJA52060B177522

Front Bumper N/A Nec 1800(SN) +

Front Bumper Sensor. N/A 285 +

Front Bumper Stickers Wrap. N/A 400(SN) +

Headlamp LH. At 4960.90 ✓

Headlamp Control Module. AP Nec 285.10 +

Headlamp Protective Film N/A ~~280(SN)~~ 180(SN)

Panel Bending ~~400~~ 200

Spry Painting 300 +

Wiring 50.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

List: 4960.90

Less 10%: 4464.81

S.N: 180.

Labour: 230

Total: 4874.81 ✓
CP/P
01 Days.