

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|--|----------------|-------|----------------------|
| | CHINA TAIPING IN | ISURANCE (S) PTE LTD | | Ref: | CS3/CTI22007009/Tqy3 |
| | 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Date: | 23/07/2022 |
| | | | | Code: | CTI |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | GBG 8348J | Veh. Inspected | l | YM 6655G |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | SNM22D205048/C02/TANKL | Excess (\$) | | 0.00 |
| | Assign From | LYNN KHONG | Assign Date | | 22/07/2022 |
| 2. | Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | | 0 |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | - | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | | | | mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | | | | mm |
| | L/H Rear Tyre | | | | mm |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 19/07/2022 | Inspection Dat | :e | 25/07/2022 |
| | Survey held at | ANN JOO MOTOR PL | | | |
| | | BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721 | | | |
| 5a. | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | |