

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOM	OTIVE SERVICES PTE LTD	Ref:	CS3/SMR22001881/Vcy3e2-1	
	60 WOODLANDS I E4SINGAPORE 75	INDUSTRIAL PARK 57705	Date:	04/08/2022	
			Code	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5301T	Veh. Inspected	SKB 9462A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/02/22/2072	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	20/07/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	HYUNDAI 145 2.4	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	KMHEC41CMBA259304	Colour	WHITE	
	Odometer	255049 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
	L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
	R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/02/2022	Inspection Date	01/03/2022	
	Survey held at	LENG WANG MOTOR			
		BLK 3007 UBI ROAD #01-414 SINGAPORE 408701			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
$\overline{}$					