

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/SMR22001881/Vcy3-1	
STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS3/SMR22001881/Vcy3
60 WOODLANDS INDUSTRIAL PARK		Date:	20/02/2022 20/07/2022
E4SINGAPORE 757705		Code:	SMR
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHB 5301T	Veh. Inspected	SKB 9462A
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/02/22/2072	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	20/02/2022 20/07/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	
Engine No.		Year of Reg.	
Chassis No.		Colour	
Odometer	KM	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/02/2022	Inspection Date	
Survey held at	LENG WANG MOTOR BLK 3007 UBI ROAD #01-414 SINGAPORE 408701		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			