

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22007016/KVCE2

Date: 29/07/2022

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP001063		
Claimant Vehicle No :	SHD5589U	Insured Vehicle No :	SKR973S		
Date of Loss:	21/07/2022	Nature of Claim:	TP	Claim No:	M2203937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5589U	Engine No:	2ZR2H15653
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU303092623
Reg. Date:	06/11/2020 (Man. Year: 2020)	Odometer:	112317 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,134.67	804.52	2,330.15	74.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	470.00	4,630.00	90.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,234.67	1,274.52	6,960.15	84.52
+ GST 7.00/7.00% (S\$)	576.43	89.22	487.21	84.52
Nett Amount (S\$)	8,811.10	1,363.74	7,447.36	84.52

INSPECTION

Date of Assignment:	27/07/2022	
Date Inspected:	22/07/2022	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,274.53

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5589U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER, REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1	*REINFORCEMENT SUB-ASSY, REAR BUMPER	Repair	332.70 FL	*- FL
3	1	*GUARD, REAR BUMPER, CENTER	Cut	374.50 FL	*374.50 FL
4	1	*SEAL, REAR BUMPER SIDE, RH	Serviceable	118.30 FL	*- FL
5	1	*RETAINER, REAR BUMPER SIDE, RH	Distorted	132.60 FL	*132.60 FL
6	1	*COVER, REAR BUMPER, LOWER	Serviceable	22.00 FL	*- FL
7	1	*COVER, DECK TRIM, REAR	Serviceable	126.70 FL	*- FL
8	1	*PANEL SUB-ASSY, BODY LOWER BACK	Repair	651.00 FL	*- FL
9	1	*REFLECTOR ASSY, REFLEX, RH	Serviceable	39.00 FL	*- FL
10	1	*LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	Serviceable	339.60 FL	*- FL
11	1	*LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (LOWER)	Serviceable	261.00 FL	*- FL
12	1	*COVER, REAR COMBINATION LAMP, RH	Serviceable	69.90 FL	*- FL
13	1	*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*60.00 FS
14	1	*SET PARKING AID	Serviceable	700.00 FS	*- FS
15	1	*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
16	1	*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,872.90	1,052.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	738.23	248.18
Total Parts (\$\$)	3,134.67	804.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
3	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
Gross Labour Cost (\$\$)			5,100.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >