

ASS. REC. BY:

REF:

TM/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

265,927/2

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

1.B. 1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHD 55894

Yr Regn: _____

11.2.0

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy Prius

c.c.

1788

Colour _____

M.P. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

112317

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTDKB3FU303092623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: _____

F: _____

195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Pir 1789

Front _____

Rear _____

R/Bal. _____

9 mm

R/Bal. _____

9

mm

L/Bal. _____

9 mm

L/Bal. _____

9

mm

D.O.A. _____

21/7/22

D.O.I. _____

22/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fines

Others

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Not Authorized
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5589U

AAD2207-093

8177453

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

22 JUL 2022

SHD5589U

JTDKB3FU303092623

200303878K

TOYOTA

PRIUS GEN 4

21/07/2022

SKR973S/TOKIO

06/11/2020

PART		LIST		
1	COVER, REAR BUMPER	\$	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70	X
1	GUARD, REAR BUMPER, CENTER	\$	374.50	✓
1	SEAL, REAR BUMPER SIDE, RH	\$	118.30	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	132.60	✓
1	COVER, REAR BUMPER, LOWER	\$	22.00	X
1	COVER, DECK TRIM, REAR	\$	126.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	651.00	X
1	REFLECTOR ASSY, REFLEX, RH	\$	39.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	261.00	X
1	COVER, REAR COMBINATION LAMP, RH	\$	69.90	X
TOTAL		\$	2,952.90	
25%		\$	738.23	
		\$	2,214.68	

Special Nett

1	REAR BUMPER SIDE CLIP	\$	60.00	✓
1SET	PARKING AID	\$	700.00	X
1SET	REAR BUMPER CLIP	\$	85.00	X
1	REAR BUMPER RETAINER CLIP	\$	75.00	X
TOTAL		\$	920.00	
TOTAL PARTS		\$	3,134.68	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5589U**AAD2207-093**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	200%
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	22%
To reinstall rear bumper parking sensor.	\$	170.00	50%
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	8,234.68	

(PART-BY-PART) Repair Days20 Days
2 days**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: