

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0490/2022/JT
DATE : 13-Jun-22
WIP : 28558

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/06/2022.

YOUR INSURED VEH NO : FBP 5785 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian
5 dys exclude 1 Sunday
Johnny Boo 22 Nov 22*

OWNER'S NAME : MR. ANG BOON CHIN
ADDRESS : 112 MCNAIR
#06-209
SINGAPORE 320112
TELEPHONE : HP +65 96979271
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070153547
VEHICLE NO : **SMW 571 T**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 30/10/2020
ENGINE NO : CZD C07007
CHASSIS NO : WAUZZZF37M1021122
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-22
PLACE OF ACCIDENT : GEYLANG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 571 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00		
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,500.00	\$	1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS SILL PANEL.	\$	4,500.00	\$	700.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,752.00	\$	2,652.00
				S	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 571 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,235.00	
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	
4	FRONT BUMPER GRILLE - RH	1	\$ 124.00	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
6	FRONT BUMPER SPOILER	1	\$ 426.00	\$ 340.80
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
8	FRONT BUMPER GUIDE SECTION- RH	1	\$ 43.00	
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00	
11	FRONT BUMPER TOP COVER	1	\$ 137.00	
12	CAUTION STICKER	1	\$ 16.00	
13	AIR COND STICKER	1	\$ 9.00	
14	FRONT FENDER - RH	1	\$ 1,445.00	\$ 1,156.00
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
16	FRONT FENDER BRACE - RH	1	\$ 98.00	
17	FRONT FENDER BRACKET - RH	1	\$ 39.00	
18	FRONT WHEEL HOUSING LINER	1	\$ 260.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
20	FRONT WHEEL HOUSING LINER COVER - RH	1	\$ 18.00	
SUB TOTAL SPARE PARTS			\$ 5,800.00	\$ 1,496.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 571 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 1,496.80
21	HEADLIGHT MOUNTING - RH	1	\$ 132.00	
22	HEADLIGHT - RH	1	\$ 5,952.00	
23	LIFT CYLINDER - RH	1	\$ 231.00	
24	LIFT CYLINDER HOSE	1	\$ 92.00	
25	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$ 452.00
26	FRONT DOOR - RH	1	\$ 3,017.00	
27	FRONT DOOR OUTER SEAL - RH	1	\$ 185.00	
28	FRONT DOOR ATTACHMENT PARTS	1	\$ 164.00	
29	FRONT DOOR CATCH - RH	1	TBC	
30	FRONT DOOR COVER - RH	1	\$ 283.00	\$ 226.00
31	WING MIRROR MOUNTING - RH	1	\$ 2,278.00	
32	WING MIRROR CAP - RH	1	\$ 203.00	
33	WING MIRROR GLASS - RH	1	\$ 1,052.00	
34	ALUMINIUM RIM	1	\$ 1,414.00	\$ 1,131.20
35	RUBBER VALVE	1	\$ 4.00	\$ 2.96
36	NOISE INSULATION	1	\$ 515.00	
37	STONE CHIP	S/N	\$ 180.00	
38	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 22,418.00	\$ 3,308.96
TOTAL LABOUR CHARGES			\$ 9,752.00	\$ 2,652.00
GRAND TOTAL			\$ 32,170.00	\$ 5,960.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-04/11/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT