

ASS. REC. BY:

REF:

CCG/CTI 22007029/Dg2

ASSIGNMENT

COE Jan 2029

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

98

days

Res.:

Y/N or No

Lum Sum:

71P

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

8HVA 4053X

Yr Regn:

Jan / 2021

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime-Mover /

Truck / Trailer or

Make:

Hyundai Ionix

cc

1580

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

208448

T/Radio:

Insured / Std / NI / NA

Eng/No:

G4LEKU418459

C/No:

KMHC851CVLU-192331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

23/07/2022

D.O.I.

26/07/2022

Survey held at

27 Jost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Ching Keping SLM 92252

22/11/22

Jman 71P 14,899.76 with 4 days 2 m

Date/Time, File Pass to?



Prel. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + \$ = \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.J. (\$)

Add Fee:



Site Insp. (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Jul-22

INSURANCE: China Taiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 4053 X

Description	Qty	List Price	Amount
Boot Lid <i>st</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>hec</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>HH</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>hec</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>hec</i>	1	\$ 24.30	\$ 24.30
Emblem-Ionic <i>hec</i>	1	\$ 31.30	\$ 31.30
Boot Lid Lamp(LH) <i>HH</i>	1	\$ 822.00	\$ 822.00
Boot Lid Trimboard <i>HH</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>HH</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HH</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH) <i>HH</i>	1	\$ 92.50	\$ 92.50
Boot Lid Glass Upper Moulding <i>HH</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HH</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>CRACK</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>CRACK</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH) <i>st</i>	1	\$ 188.10	\$ 188.10
Antenna Assy-SMARTK outer <i>HH</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>mainly CRACK</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH) <i>broken</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>hec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>mainly broken</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH) <i>broken</i>	1	\$ 123.10	\$ 123.10
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH) <i>broken</i>	1	\$ 82.90	\$ 82.90
Rear Bumper Towing Cover <i>dislodged</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>HH</i>	1	\$ 328.60	\$ 328.60
Tail Lamp(LH) <i>mainly CRACK/broken</i>	1	\$ 935.40	\$ 935.40
Tail Lamp Quarter Panel(LH) <i>Dent</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>Dent</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>HH</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
Rear tray tools box LH <i>HH</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>HH</i>	1	\$ 354.20	\$ 354.20
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (LH) <i>dislodged torn</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (LH) <i>HH</i>	1	\$ 165.50	\$ 165.50
Rear Fender Corner inner upper garnish (LH) <i>HH</i>	1	\$ 486.70	\$ 486.70
Rear Fender Air-Duct (LH) <i>defunct</i>	1	\$ 87.30	\$ 87.30
Rear Fender Trim Board (LH) <i>st/defunct</i>	1	\$ 788.75	\$ 788.75

REAR FENDER TRIM BOARD TOP GARNISH (LH) <i>HH</i>	1	\$167.90	\$ 167.90
Assy BSD Blind Spot Radar (LH) <i>monny 1st / Dem</i>	1	\$ 1,784.40	\$ 1,784.40
Rear Tyre Rim (LH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (LH) <i>cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>Dem</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(LH) <i>distorted</i>	1	\$ 265.40	\$ 265.40
Rear Assist (LH) <i>distorted</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(LH) <i>distorted</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (LH) <i>HH</i>	1	\$ 175.60	\$ 175.60
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(LH) <i>distorted</i>	1	\$ 239.50	\$ 239.50
Rear Lower Arm(LH) <i>distorted</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (LH) <i>distorted</i>	1	\$ 538.10	\$ 538.10
SUB TOTAL			\$ 22,555.25
LESS 20%			\$ 4,511.05
DISCOUNTED TOTAL			\$ 18,044.20
Boot Lid Comfort Logo & Tel No. Sticker <i>HCC</i>	SN 1	\$ 35.00	\$ 35.00
Boot Lid Cab Link No. Sticker <i>HP</i>	SN 1	\$ 30.00	\$ 30.00
Boot Lid Advertisement Logo <i>HCC</i>	SN 1	\$ 100.00	\$ 100.00
Rear Windscreen Sealant <i>HCC</i>	SN 2	\$ 46.00	\$ 92.00
Rear Bumper Advertisement Logo <i>HCC</i>	SN 1	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat <i>HCC</i>	SN 1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>Dem</i>	SN 1	\$ 180.00	\$ 180.00
Rear Fender Advertisement Logo (LH) <i>HCC</i>	SN 1	\$ 100.00	\$ 100.00
Rear Tyre(LH) <i>SVC</i>	SN 1	\$ 216.00	\$ 216.00
SUB TOTAL			\$ 853.00
Labour Charge			
Panel Beating	1	\$2,000.00	\$2,000.00
Spray Painting Charge	1	\$1,800.00	\$1,800.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	1	\$80.00	\$80.00
Four Wheel Alignment	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	\$550.00
TOTAL LABOUR			\$6,290.00
ESTIMATE TOTAL			\$25,187.20

15,203.45

12,162.76

607.00

800/-
700/-
30/-
40/-
40/-
80/-
80/-
40/-
150/-
40/-
150/-
60/-
150/-

2130.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantity will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

26/07/2022 @ 1030am

Not Author 9

P/Part

8 days.



LKK Auto

P/P 14,899.76

Photo of repair

with damaged

parts.



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer: LIM TAN
 Company: 01-42
 License NO: SHA 4053X
 Odometer:

Date: 7/26/2022 11:23 AM
 VIN
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT
 HYUNDAI, IONIQ (AE HEV) Hybrid, 17-17 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°56'	4°00'	5°00'	5°00'
		Right	4°55'	4°00'	5°00'	5°00'
	Camber	Left	-0°30'	-0°53'	0°07'	-0°24'
		Right	-0°36'	-0°53'	0°07'	-0°30'
	Toe	Left	-0°09'	-0°03'	0°09'	-0°09'
		Right	-0°06'	-0°03'	0°09'	-0°06'
Total		-0°15'	-0°06'	0°18'	-0°15'	
Rear	Camber	Left	-2°42'	-1°42'	-0°42'	-2°36'
		Right	-1°24'	-1°42'	-0°42'	-1°24'
	Toe	Left	0°15'	-0°02'	0°10'	0°15'
		Right	0°18'	-0°02'	0°10'	0°18'
		Total	0°33'	-0°04'	0°20'	0°33'
	Thrust Angle		-0°02'	----		-0°02'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13°47'	13°30'	14°30'	13°47'
	Right		14°14'	13°30'	14°30'	14°14'
Included Angle	Left		13°17'	----	----	13°23'
	Right		13°38'	----	----	13°44'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-1mm	----	----	-1mm
	Rear		-2mm	----	----	-2mm
Track Width Diff.			-13mm			-13mm
Wheel Base Diff.			0mm			0mm
Front Ride Height	Left		----	373mm	393mm	----
	Right		----	373mm	393mm	----
Rear Ride Height	Left		----	372mm	392mm	----
	Right		----	372mm	392mm	----
Frame Angle						----

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA4053X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Jul 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU418459
Chassis No.:	KMHC851CVLU192331
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,602.00
Original Registration Date:	28 Jan 2021
First Registration Date:	28 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2029
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$30,510.00
COE Rebate Amount:	\$24,408.00
Total Rebate Amount:	\$28,158.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jul 2022

OK