



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 23-07-2022

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

VEHICLE NO. : YP6567L

ACCIDENT DATE : 18-07-2022 16:00

THIRD PARTY REF. : YN2914E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE YP6567L MITSUBISHI FUSO FK62FMZ1RDEB

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN RUBBER	700.00
2	1	FRONT WINDSCREEN GLASS	2100.00
3	1	FRONT WIPER PANEL	260.00
4	1	FRONT WIPER HANDLE BRACKET RH	165.00
5	1	FRONT PANEL	2800.00
6	1	FRONT PANEL FUSO EMBLEM	290.00
7	2	FRONT PANEL LOCK TOP @\$120.00	240.00
8	2	FRONT PANEL LOCK LOWER@\$27.00	54.00
9	2	FRONT PANEL LOCK BRACKET@\$65.00	130.00
10	1	FRONT PANEL LOCK CABLE 1	280.00
11	1	FRONT PANEL LOCK CABLE 2	280.00
12	1	FRONT GRILLE	690.00
13	1	FRONT GRILLE BRACKET	50.00
14	1	FRONT HEADLAMP RH	550.00
15	2	FRONT HEADLAMP RIM @\$120.00	240.00
16	1	FRONT HEADLAMP BRACKET RH	265.00
17	2	FRONT CORNER PANEL@\$650.00	1300.00
18	1	FRONT BUMPER	1110.00
19	2	FRONT BUMPER BRACKET @\$400.00	800.00
20	1	FRONT CENTRE BRACKET	0.00
21	1	FRONT CABIN BAR	600.00
22	1	FRONT CABIN BAR BRACKET@\$550.00	1100.00
23	1	FRONT CABIN SEAL@\$30.00	60.00
24	1	FRONT CABIN SIDE BRACKET RH	600.00
25	1	FIRE WALL	5800.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : YP6567L
ACCIDENT DATE : 18-07-2022 16:00
THIRD PARTY REF. : YN2914E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	SPARE TANK	250.00
27	1	BRAKE FULD TANK	250.00
28	1	AIR CON BLOWER	910.00
29	1	HEATER UNIT	2400.00
30	1	DASHBOARD REINFORCEMENT	2100.00
31	1	WASTER PUMP	950.00
32	1	THEMOSTATE	105.00
33	1	FLOOR PANEL	1280.00
34	1	CARPET	850.00
			29,559.00
			ADD 10 %
			2,955.90
			TOTAL (A)
			32,514.90

SPECIAL NETT ITEMS

1	1	ERP STICKER	15.00
2	1	FRONT NUMBER PLATE	40.00
3	1	REAR HYDRAULIC LH	3500.00
			TOTAL (C)
			3,555.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00
2	1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	120.00
3	1	TO REMOVE/REFIT DASHBOARD	250.00
4	1	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	180.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : YP6567L

ACCIDENT DATE : 18-07-2022 16:00

THIRD PARTY REF. : YN2914E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
5	1	TO REMOVE/REFIT CARPET, CUSHION AND ETC	180.00
6	1	TO REMOVE ALL NECESARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	1500.00
7	1	SPRAYPAINTING CHARGES	980.00
TOTAL (D)			3,260.00
ESTIMATE TOTAL			39,329.90