

Date: 22/07/2022

Vehicle No: SMM9006C

Model: AUDI Q5 SPORT 2.0 TFSI

Chassis: WAUZZZFJ2J2171074

Reg.Year: 2018

Third Party Insurer: AIG

Third Party Veh No: SMW3721H

Date of Accident: 19/07/2022

Estimator: KIT

Surveyor:

*Not Notarized
11 Rmp &
Recovery After Pain
3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>Bul/cm</i>	\$1,584.70
2	REAR BUMPER LOWER	1	<i>cm</i>	\$1,067.40
3	REAR BUMPER DIFFUSER	1		\$774.50
4	REAR BUMPER REFLECTOR LAMP LH	1	<i>cm</i>	\$583.80
5	REAR BUMPER REFLECTOR LAMP RH	1	<i>cm</i>	\$583.80
6	REAR BUMPER REVERSE SENSOR	4	\$242.60	<i>in</i> \$970.40
7	REAR BUMPER REINFORCEMENT	1		\$825.10
SUB TOTAL				\$6,389.70
LESS 5%				-\$319.49
PARTS TOTAL				\$6,070.22

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>mm</i> \$100.00
2	REAR BUMPER RIVET	1		\$100.00
S/N TOTAL				\$200.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.	\$400.00	<i>250</i>
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.	\$400.00	<i>✓</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	<i>601</i>
TO CHECK WIRING & ELECTRICAL DIAGNOSTIC	\$100.00	<i>7</i>

LABOUR TOTAL \$1,020.00

KIT TOTAL \$7,290.22