

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 22/07/2022

Vehicle No: SMM9006C

Model: AUDI Q5 SPORT 2.0 TFSI

Chassis: WAUZZZFJ2J2171074

Reg. Year: 2018

Third Party Insurer: AIG

Third Party Veh No: SMW3721H

Date of Accident: 19/07/2022

Estimator: KIT

Surveyor:

*Not Notarized
61 Lamp & 3350h
Running After Rain
3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>1525.60</i>	1	<i>Bul/cm</i>	\$1,584.70
2	REAR BUMPER LOWER <i>856.80</i>	1	<i>cm</i>	\$1,067.40
3	REAR BUMPER DIFFUSER	1		<i>in</i> \$774.50
4	REAR BUMPER REFLECTOR LAMP LH <i>559.10</i>	1	<i>cm</i>	\$583.80
5	REAR BUMPER REFLECTOR LAMP RH <i>559.20</i>	1	<i>cm</i>	\$583.80
6	REAR BUMPER REVERSE SENSOR	4	\$242.60	<i>in</i> \$970.40
7	REAR BUMPER REINFORCEMENT	1		<i>R</i> \$825.10
SUB TOTAL				\$6,389.70
LESS 5%				-\$319.49
PARTS TOTAL				\$6,070.22

*11
X
11
X*

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>mm</i> \$100.00
2	REAR BUMPER RIVET	1		<i>nn</i> \$100.00
S/N TOTAL				\$200.00

*1
X*

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$400.00 *250*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$400.00 *✓*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$120.00 *60*

TO CHECK WIRING & ELECTRICAL DIAGNOSTIC *nn* \$100.00 *X*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR TOTAL \$1,020.00

TOTAL \$7,290.22

KIT