

SERVICE ESTIMATE

TEST - C00018 SL: SERVICE/PARTS SALES - DUCATI
 Brillet Eric Nicolas
 11, 11, 11 Road

Singapore
 Singapore 217024

Used by : Tony Alfred Desire D
 Consultant : C982
 Remarks : Mr Brillet Eric Nico

Inv.No. : 0
 Inv.date : 22/07/2022
 WIP No. : 33645
 Veh. In/Out:
 Tel.No. : Mobile: 94329234
 Reg.No. : FBK4323K / SCR
 Reg.date : 12/08/2015
 Mileage : 19,886
 Chassis No. : ZDMK100AAFB003370
 Variant... : SCR FullThrottli

No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
UT A	Accident Damage Assessment		70.00	0	X	70.00	S
TED	ACCIDENT REPAIR		0.00	0			S
CD	To replace damaged parts caus	3 x 1200	3600.00	0		3600.00	/
	COVER, EXHAUST (LH) - RV	1.0 EA	192.00			192.00	/
	COVER, EXHAUST (RH) - RV	1.0 EA	189.40			189.40	/
	SCREW - NC	6.0 EA	2.30			13.80	/
	HEAT GUARD (BANK) - RV	1.0 EA	133.00			133.00	/
	WASHER - NC	2.0 EA	0.30			0.60	/
	SPACER - NC	1.0 EA	2.40			2.40	/
	QUICK FASTENING - NC	2.0 EA	1.30			2.60	/
	NUT, SPRING M5 - NC	1.0 EA	4.10			4.10	/
	FINAL SILENCER - X NN	2.0 EA	576.10			1152.20	S
	CLAMP - X NN	2.0 EA	41.30			82.60	S
	REAR-VIEW MIRROR - OR	1.0 EA	161.60			161.60	/
	PLUG (BANK) - RV	2.0 EA	12.50			25.00	/
	HANDLEBAR - BT	1.0 EA	354.50			354.50	/
	PIPE, EXHAUST C - ALU	1.0 EA	353.80			353.80	/
	SPRING EXHAUST - RV	3.0 EA	25.10		X NN	75.30	S
	LEVER, FRONT BR - X NN	1.0 EA	265.10			265.10	/
	REAR WHEEL RIM - CUT	1.0 EA	2067.80			2067.80	S
	REAR SWINGING A - NC	1.0 EA	1893.60			1893.60	/
	SCREW TBEIF M4X - NC	3.0 EA	3.70			11.10	/
	WASHER 4.5X9X0. - NC	3.0 EA	1.50			4.50	/

UK Auto Consultants hence notify the Repairer of the following:

- * Survey before/after spray painting
- * Display damaged part(s) during resurvey
- * All prices are subject to confirmation
- * The survey is on a "Without Prejudice" basis
- * The confirmation(s) is allowed
- * The repairer must be resurveyed and
- * The repairer must be resurveyed and

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

Co. Reg. No. 199501400R / GST Reg. No. M98906204

SERVICE ESTIMATE

SL: SERVICE/PARTS SALES - DUCATI

Eric Nicolas
Mr. Brillet Eric Nico

Inv. No. : D 0 Page 2
Inv. date : 22/07/2022
WIP No. : 33645
Veh. In/Out:
*Tel. No. : Mobile: 94529234
Reg. No. : FBK4323K / SCR
Reg. date : 12/08/2015
Mileage : 19,886
Chassis No. : ZDMK100AAFB003370
Variant... : SCR FullThrottl

by : Tony Alfred Desire D
Consultant : 0988
Mr. Brillet Eric Nico

Description	CCC Mech Qty	Price	Disc%	Pkg	Amount G
PLATE - <i>ne</i>	2.0 EA	1.60			3.20
PLATE - <i>ne</i>	1.0 EA	1.60			1.60
CHAIN SLIDER - <i>ne</i>	1.0 EA	25.20			25.20
CHAIN ADJUSTMEN - <i>ne</i>	1.0 EA	7.60			7.60
SPRING RING - <i>ne</i>	2.0 EA	0.60			1.20
REAR RIGHT FOOT - <i>ne</i>	1.0 EA	74.00			74.00
CIRCLIP E-TYPE - <i>ne</i>	2.0 EA	1.00			2.00
PLATE - <i>ne</i>	2.0 EA	2.10			4.20
FOOTREST PIN - <i>ne</i>	1.0 EA	3.70			3.70
HOLDER - <i>ne</i> (Front hook)	1.0 EA	59.10			59.10
FOOTREST PIN - <i>ne</i>	1.0 EA	9.60			9.60
FOOTREST, FRONT - <i>ne</i>	1.0 EA	74.00			74.00
SPRING, FOOTRES - <i>ne</i>	1.0 EA	3.30			3.30
O-RING - <i>ne</i>	2.0 EA	0.40			0.80
NUT MS - <i>ne</i> x <i>nn</i>	1.0 EA	0.60			0.60
DAMPER FOOTREST - <i>ne</i>	1.0 EA	30.80			30.80
BALL - <i>ne</i>	1.0 EA	0.60			0.60
SPRING - <i>ne</i>	1.0 EA	2.20			2.20
BRAKE CONTROL L - <i>ne</i> (Stop) - <i>ne</i>	1.0 EA	133.00			133.00
RH FOOT PEG HOL - <i>ne</i> (Stop hook) - <i>ne</i>	1.0 EA	384.00			384.00

Steve (LKK)
25/7/22, 11.00

ne ne

3 4, PIP, M Bel SM

Labour Total
Parts Total
package Total

3,670.00
7,805.70
0.00

Amount 11,475.70
GST @ 7 % 803.30
Total Amount 12,279.00
less Amt Paid 0.00
Nett Amount 12,279.00

ST: S=StdRated; O=OutOfScope; Z=ZeroRated
Service Estimates are valid for 10 days from the above date.
This is a computer generated invoice, no signature is required.

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930