



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2206084

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 30/09/2022
Reference CS/EQI22007034/Ecy3m4
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. FBK 4323K
Insured Veh. GBH 2726K
Claim No. DM22HO01223
Policy No.
Accident Date 25/06/2022
Inspection Date 25/07/2022

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI22007034/Ecy3m4 Date: 30/09/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 2726K	Veh. Inspected	FBK 4323K
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO01223	Excess (\$)	0.00
Assign From	NEO JIE SI	Assign Date	22/07/2022
2. Vehicle Particulars & Condition			
Make & Model	DUCATI SCRAMBLER	c.c	803
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZDMK100AAFB003370	Colour	BLACK
Odometer	2700 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	180/80 R18	BRIDGESTONE	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 R17	BRIDGESTONE	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/06/2022	Inspection Date	25/07/2022
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 4323K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, EXHAUST (SN)	CUT	192.00	192.00
1	COVER, EXHAUST (SN)	CUT	189.40	189.40
6	SCREW @\$2.30 (SN)	NECESSARY	13.80	13.80
1	HEAT GUARD (SN)	CUT	133.00	133.00
2	WASHER @\$0.30 (SN)	NECESSARY	0.60	0.60
1	SPACER (SN)	NECESSARY	2.40	2.40
2	QUICK FASTENING @\$1.30 (SN)	NECESSARY	2.60	2.60
1	NUT, SPRING M5 (SN)	NECESSARY	4.10	4.10
2	FINAL SILENCER @\$576.10 (SN)	NOT NECESSARY	1,152.20	-
2	CLAMP @\$41.30 (SN)	NOT NECESSARY	82.60	-
1	REAR-VIEW MIRRO (SN)	BROKEN	161.60	161.60
2	PLUG @\$12.50 (SN)	CUT	25.00	25.00
1	HANDLEBAR (SN)	BENT	354.50	354.50
1	PIPE, EXHAUST C (SN)	CUT	353.80	353.80
3	SPRING EXHAUST @\$25.10 (SN)	NOT NECESSARY	75.30	-
1	LEVER, FRONT BR (SN)	CUT	265.10	265.10
1	REAR WHEEL RIM (SN)	NOT NECESSARY	2,067.80	-
1	REAR SWINGING A (SN)	CUT	1,893.60	1,893.60
3	SCREW TBEIF M4X @\$3.70 (SN)	NECESSARY	11.10	11.10
3	WASHER 4.5X9X0. @\$1.50 (SN)	NECESSARY	4.50	4.50
2	PLATE @\$1.60 (SN)	NECESSARY	3.20	3.20
1	PLATE (SN)	NECESSARY	1.60	1.60
1	CHAIN SLIDER (SN)	NECESSARY	25.20	25.20
1	CHAIN ADJUSTMEN (SN)	NECESSARY	7.60	7.60
2	SPRING RING @\$0.60 (SN)	NECESSARY	1.20	1.20
1	REAR RIGHT FOOT (SN)	CUT	74.00	74.00
2	CIRCLIP E-TYPE @\$1.00 (SN)	NECESSARY	2.00	2.00
2	PLATE @\$2.10 (SN)	NECESSARY	4.20	4.20
1	FOOTREST PIN (SN)	NECESSARY	3.70	3.70
1	HOLDER (SN)	CUT	59.10	59.10
1	FOOTREST PIN (SN)	NECESSARY	9.60	9.60

Report Ref No. CS/EQI22007034/Ecy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOOTREST, FRONT (SN)	CUT	74.00	74.00
1	SPRING. FOOTRES (SN)	NECESSARY	3.30	3.30
2	O-RING @\$0.40 (SN)	NECESSARY	0.80	0.80
1	NUT M8 (SN)	NOT NECESSARY	0.60	-
1	DAMPER FOOTREST (SN)	NECESSARY	30.80	30.80
1	BALL (SN)	NECESSARY	0.60	0.60
1	SPRING (SN)	NECESSARY	2.20	2.20
1	BRAKE CONTROL L (SN)	CUT	133.00	133.00
1	RH FOOT PEG HOL (SN)	CUT	384.00	384.00
3	COMPLETE SPRING @\$25.10 (SN) (ADDITIONAL)	NECESSARY	75.30	75.30
2	THRUST WASHER @\$1.00 (SN) (ADDITIONAL)	NECESSARY	2.00	2.00
2	THRUST WASHER @\$1.70 (SN) (ADDITIONAL)	NECESSARY	3.40	3.40
1	CHAIN LINK (SN) (ADDITIONAL)	NECESSARY	15.80	15.80
			7,902.20	4,523.70
	LABOUR			
	ACCIDENT DAMAGE ASSESSMENT.	NOT NECESSARY	70.00	-
	ACCIDENT REPAIR. (NPA)	NOT NECESSARY	-	-
	TO REPLACE DAMAGED PARTS CAUS.		3,600.00	3,600.00
			3,670.00	3,600.00
GRAND TOTAL			11,572.20	8,123.70
RECOMMENDED COST OF REPAIRS				8,123.70

Report Ref No. CS/EQI22007034/Ecy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



WEARNES AUTOMOTIVE PTE LTD

45 LENG KEE ROAD SINGAPORE 159103

Tel: +65 64304930 Fax: +65 6474 0853 www.ducatisingapore.com

Repair Estimate

Date	26 Sep 2022
Bike Number	FBK4323K
Chassis No.	ZDMK100AAFB003370
Customer	Mr Brillet Eric Nicolas
Address	
Email	

Model	SCR FT
Mileage	
Contact	
Svc. No.	
Youtech	
Technician	

No.	Labour Code	Description	Qty	Unit Price	Amount
		Sub-Total			

No.	Part Number	Description	Qty	Unit Price	Amount
1		COMPLETE SPRING NEC	3	\$25.10	\$75.30
2		THRUST WASHER NEC	2	\$1.00	\$2.00
3		THRUST WASHER NEC	2	\$1.70	\$3.40
4		CHAIN LINK NEC	1	\$15.80	\$15.80
		Sub-Total			\$96.50

1. This estimate is compiled with visual inspection on the above mentioned motorcycle.

2. During the repair process, additional parts and labour may be required to complete the repairs works. A supplementary estimate shall be created accordingly.

3. The undersigned signature represents the acceptance of this estimate and the permission to proceed with repair works.

Signature: _____

Total Labour:	\$0.00
Total Parts:	\$96.50
GST:	\$6.76
Grand Total:	\$103.26

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/07/2022 13:49 (SGT)
Reported by	Both
Date of Accident	25/06/2022 16:00 (SGT)
Exact Location of Accident	63A Carlisle Rd, Singapore 219634
Additional Location Information	PARKED AT 63A CARLISLE ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBK4323K

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	BRILLET ERIC NICOLAS
NRIC No	SXXXX535J
Email Address	ERIC@EKKKO.COM
Mobile Phone No	(Phone) +65-94529234
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Ducati
Model	SCRAMBLER FULL THROTTLE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	803

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MC/00837398/01

DRIVER

Name of Driver	BRILLET ERIC NICOLAS
NRIC No	SXXXX535J
Date Of Birth	01/02/1971
Occupation	Indoor

Date Of Driving Pass	08/12/1994
Driving experience	27 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94529234
Alt. Phone Number	-
Email Address	ERIC@EKKKO.COM
Address	63A CARLISLE ROAD
Address complement	-
Postcode	219634
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER THE SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH2726K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	MOHAMED BASHIR BIN ABDUL RAHIM
NRIC No	SXXXX611I

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

My moto was parked, at the side of the road, next to my house as usual. It had a moto cover as well. At about 4 PM on Saturday 25/06/2022, a FEDEX Delivery Van stopped by the side of the same road (CARLISLE RD) to drop off a delivery then quickly moved off and subsequently hit the rear tyre of my moto and caused it to luffle hard on its right side (exhaust side). The driver immediately stopped and parked a few metres in front to contact me. I was home at the time and witnessed the accident from my balcony window. I came down to inspect the damage after the bike was put upright. Saw the motor was broken on right side, exhaust muffler impact and dented, main footpeg for brake severely dented, right passenger footpeg scratched, and right throttle assembly damaged on handle bar. Bike was able to start and ride but throttle very light and right brake very hard to press.

Driver assisted me and gave me all his details:

IC: 51687611L

NAME: MOHAMED BASHIR BIN ABDUL RAHIM

CAR: FEDEX VAN GBH2726K

TIME OF ACCIDENT: ~ 4 PM SATURDAY 25/06/2022

PLACE OF ACCIDENT: 63A CARLISLE ROAD

MY DETAILS (MOTO OWNER)

IC: 57176535T

NAME: BRILLET ERIC NICOLAS

MOBILE: 9452 9234

EMAIL: ERIC@EKKKO.COM

MOTO: DUCATI SCRAMBLER FULL THROTTLE / FBK 4323K

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBK 4323K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBK 4323K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

