

ASS. REC. BY:

Stere

CS/40122007036/Ecy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV 15534 Yr Regn: 18/19/20Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216c.c. 1499Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading 14/4

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAGK170305R41568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 5 mm

Rear

R/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 17/7/22D.O.I. 27/1/22Survey held at PerformanceDes. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-117K
PR-58,982
NR-88,018

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

SMV1553U

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 9

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -
Wu Pei Kam
12A Marsiling Lane
#08-57

Singapore 731012

- ACCOUNT - 115
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION	VALUE
To replace front bumper, bonnet, both left & right fender, both left & right wheel housing with chassis including to pull & straighten both chassis before cutting and to knock out dented area	14,450 17,000.00
To respray front bumper, bonnet, both left & right fender and both left & right wheel housing with chassis	4909 5,168.00
To carry out body cavity preservation (3X)	336 354.00
To carry out body cavity preservation. (Per panel).	112 118.00
To tow accident vehicle to PML workshop.	150.00
To send vehicle with new short engine to LTA for inspection.	? 191.00
Being charge for LTA inspection fees.	? 80.00
To remove and install engine and auto transmission to facilitate jacking of chassis and mounting of car on celette bench including to replace damaged parts.	1569 1,652.00
To replace new short engine and adjust engine timing accordance to BMW specification.	? 8,496.00
To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).	784 826.00
To replace auxiliary radiator assembly including pressure test, bleed cooling system and conduct check for leak.	728 767.00
To replace charge air cooler including conduct check for leak and proper function.	504 531.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 9

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION	VALUE
To replace engine mounting including re-alignment of engine block to body frame.	645 679.00
To replace gearbox mounting including re-alignment of gearbox to cross member and propeller shaft system.	? 679.00
To remove and install front suspension for inspection and replace damaged parts.	? 2,655.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (2x).	1008 1,062.00
To remove and install hydraulic unit for DSC to facilitate repair.	504 531.00
To perform brake test including bleed brake system with DSC and conduct check for leak.	952 1,003.00
To mount accident vehicle on celette bench or Car-O-liner to facilitate re-alignment of body / chassis accordance with BMW specification.	2802 2,950.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	504 531.00
To replace front windscreen glass.	545 574.00
To remove and install IU unit bracket.	29 31.00
To conduct water leak tests.	71 75.00
To supply and install front windscreen solar film.	504 531.00
To replace front dashboard panel and conduct check for proper function.	757 797.00
To remove and install front seats and carpet to facilitate repair.	? 870.00
To remove and install fuse box at the front section to facilitate repair.	504 531.00
To replace left headlight.	456 481.00
To replace right headlight.	456 481.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

Page No. : 3 of 9

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION

VALUE

To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series).

952 1,003.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To replace both front seat belts and tensioners including reset and conduct check for proper function.

504 531.00

To replace roof top headlining and both ITS head air bags including reset and conduct check for proper function.

967 1,018.00

To replace front dashboard passenger air bag including reset and conduct check for proper function.

574 531.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 177.00

To supply front emboss number plate.

83.00

Sundries.

150.00

Total Labour 1: 53,464.00

DESCRIPTION

QTY

PRIC

VALUE

Oil filter	1	854.30	854.30
(S/L) RP POWERTRAIN	1	16,760.10	16,760.10
ENGINE COVER	1	361.25	361.25
SOUND INSULATION	1	74.75	74.75
RIBBED V BELT	1	53.25	53.25
Intake manif	1	837.60	837.60
EXCH TURBO CHARGER	1	4,074.55	4,074.55
AIR INTAKE DUCT	1	180.50	180.50
INTAKE SILENCER	1	462.30	462.30
EXTERNAL RADIATOR	1	527.20	527.20
RADIATOR	1	878.70	878.70
ROCK GUARD	1	34.75	34.75
HOSE RADIATOR	1	86.20	86.20
HOSE RADIATOR	1	86.20	86.20
HOSE RADIATOR ENGINE	1	123.95	123.95
HOSE RADIATOR TOP THERMOSTAT	1	107.75	107.75
EXPANSION TANK	1	194.90	194.90
FAN HOUSING WITH FAN 600W	1	1,436.50	1,436.50
CHARGE AIR COOLER	1	592.55	592.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 4 of 9

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION	QTY	PRIC	VALUE
STABILIZER LINK	1	77.20	77.20
ENGINE MOUNT	1	252.05	252.05
GEARBOX MOUNT	1	219.15	219.15
RP DOUBLE CLUTCH TRANSMISSION	1	17,924.95	17,924.95
FRT AXLE SUPPORT	1	1,489.20	1,489.20
(DG) AIRBAG MODULE DRIVER'S SIDE	1	1,499.85	1,499.85
FRT RIGHT SPRING SUPPORT WITH VIN	1	385.00	385.00
FRT LH FENDER	1	639.70	639.70
FRT RH FENDER	1	639.70	639.70
Supporting s	1	173.00	173.00
RH SUPPORTING STRUT WHEEL HOUSE EXT	1	173.00	173.00
LH INTERIOR SUPPORTING STRUT WHEEL	1	173.00	173.00
Supporting s	1	173.00	173.00
Extension wheel housing strut	1	173.00	173.00
RH EXTENSION WHEEL HOUSING STRUT	1	173.00	173.00
LH CROSS SUPPORT SIDE PANEL	1	33.10	33.10
RH CROSS SUPPORT SIDE PANEL	1	33.85	33.85
LH TOP SIDE PANEL BRACKET	1	42.45	42.45
RH TOP SIDE PANEL BRACKET	1	42.45	42.45
LH INTERIOR ENGINE SUPPORT	1	171.05	171.05
RH INTERIOR ENGINE SUPPORT	1	171.05	171.05
Spring strut (RH wheel)	1	427.80	427.80
BONNET LH HINGE	1	115.85	115.85
BONNET RH HINGE	1	115.85	115.85
BONNET	1	1,268.25	1,268.25
FRT BUMPER LH INSERT	1	14.20	14.20
FRT BUMPER RH INSERT	1	14.20	14.20
FRT LH SIDE PANEL TOP MOUNTING	1	18.90	18.90
FRT RH SIDE PANEL TOP MOUNTING	1	19.00	19.00
FRT LH TOP DEFORMATION ELEMENT	1	106.75	106.75
FRT RH TOP DEFORMATION ELEMENT	1	106.75	106.75
LH FOG LAMP SUPPORT	1	80.55	80.55
RH FOG LAMP SUPPORT	1	80.55	80.55
GRATE CENTRE CLOSED (LINES/PDC)	1	161.55	161.55
FRT BUMPER TOP CARRIER	1	400.80	400.80
LH FINISHER	1	50.90	50.90
RH FINISHER	1	50.90	50.90
LH MOLDING (SPORT)	1	62.55	62.55
IMPACT ABSORBER TOP	1	59.60	59.60
TRIM STRIP CENTRE (SPORT)	1	55.05	55.05
FRT BUMPER FLAP TOWING EYE PRIMED	1	43.95	43.95
FRT BUMPER PRIMED PANEL (PMA)	1	929.20	929.20
LH GRID LATERAL (LINES/PDC)	1	96.95	96.95
RH GRID LATERAL (LINES/PDC)	1	96.95	96.95
FRT LH GRILLE (SPORT)	1	113.15	113.15
FRT RH GRILLE (SPORT)	1	113.15	113.15
Bracket for gas spring	1	16.20	16.20
LH BRACKET FOR GAS SPRING	1	16.20	16.20
GAS FILLED STRUT ENGINE COMPARTMENT	2	146.85	293.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 5 of 9

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION	QTY	PRIC	VALUE
CATCH BRACKET	2	56.00	112.00
LH LOCK F HOOD	1	93.30	93.30
RH LOCK F HOOD	1	93.30	93.30
REAR BOWDEN CABLE ENGINE COMP. LID	1	36.65	36.65
FRT WINDSCREEN (KAFAS)	1	838.90	838.90
COVER WINDSHIELD TOP	1	38.45	38.45
LH DRIP MOULDING	1	74.60	74.60
RH DRIP MOULDING	1	74.60	74.60
RH COLUMN A COVER (EVERESTGRAU)	1	80.40	80.40
LH COLUMN A COVER (EVERESTGRAU)	1	86.85	86.85
Cover column	1	86.85	86.85
Cover column	1	84.35	84.35
Cover column	1	84.35	84.35
Cover column	1	84.30	84.30
ROOFLINER STANDARD ROOF (EVERESTGRA	1	74.70	74.70
(S/L) SOUND INSULATION F APRON L136	1	63.45	63.45
INSTRUMENT PANEL W DEC.STITCH (SCHW	1	1,204.25	1,204.25
LH SUPPORT HEADLIGHT ARM	1	74.85	74.85
RH SUPPORT HEADLIGHT ARM	1	2,091.50	2,091.50
LH SUPPORT	1	134.25	134.25
RH SUPPORT	1	134.25	134.25
FRONT CROSSLINK	1	155.70	155.70
FRONT PANEL V STRUT	1	155.70	155.70
AIR DUCT	1	129.50	129.50
RH GASKET HEADLIGHT AND HOOD	1	126.80	126.80
PLAQUE 82MM	1	276.05	276.05
FRT ENGINE HOOD SEALING	1	276.05	276.05
REAR ENGINE HOOD SEALING	1	19.90	19.90
FRT LH FENDER SEALING	1	72.85	72.85
FRT RH FENDER SEALING	1	72.85	72.85
LH ENGINE COMP. LID SEAL MOUNTING	1	52.85	52.85
RH MOUNTING SEAL ENGINE COMP. LID	1	52.85	52.85
LH GASKET HEADLIGHT AND HOOD	1	34.55	34.55
Slot cover	1	34.55	34.55
(S/L) REPL. SILICON PAD FOR RAIN SE	1	13.80	13.80
SENSOR RAIN/LIGHT/SOLAR/MISTING OVE	1	13.95	13.95
FILLER PIPE WASH CONTAINER	1	27.25	27.25
LH HEADLIGHT LED TECHNOLOGY	1	41.75	41.75
RH HEADLIGHT LED TECHNOLOGY	1	44.65	44.65
CONTROL UNIT FRT LIGHT ELECTRONICS	1	44.65	44.65
LH LED MOD. TURN IND./DAYTIME DRIVI	1	387.35	387.35
RH LED MOD. TURN IND./DAY DRIVE LIG	1	45.35	45.35
CONDENSER AIR CONDITIONING WITH DRI	1	2,399.10	2,399.10
SUCTION PIPE (R134A)	1	2,399.10	2,399.10
PRESSURE HOSE F EVAPORATOR CONDENSE	1	911.80	1,823.60
PRESSURE HOSE COMPRESSOR-CONDENSER	1	234.60	234.60
ULTRASONIC SENSOR BLACK	1	234.60	234.60
DECOUPING RING PDC TORQUE CONVERTER	1	1,032.05	1,032.05
SET ADHESIVE PADS FOR ACE 2.0	1	223.25	223.25
	1	196.45	196.45
	1	178.60	178.60
	4	254.05	1,016.20
	4	5.30	21.20
	1	37.35	37.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 6 of 9

Estimate No. : b1 62585
Date Estimated : 19/07/2022
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMV1553U	WBA6V120305R41568	18/09/2020	216i Gran Tourer	25998

DESCRIPTION	QTY	PRIC	VALUE
FRT LOWER STRAP / NK	1	205.60	205.60
(DG) FRT LH UPPER BELT (SCHWARZ) / Jwd	1	344.50	344.50
(DG) FRT RH UPPER BELT (SCHWARZ) / Jwd	1	344.50	344.50
(DG) AIRBAG FOR FRT PASSENGER / BR	1	1,148.05	1,148.05
(DG) LH HEAD AIRBAG / BR	1	675.35	675.35
(DG) RH HEAD AIRBAG / BR	1	675.35	675.35
(DG) CLEANER R1 (100ML) / NK	1	26.15	26.15
(DG) W/SCREEN SEALANT (COLD 1 HOUR) / NK	2	131.55	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML) / NK	1	27.85	27.85
(S/L) BMW DCTF-2 (1 LITRES) / NK	4	65.20	260.80
(S/L) ANTI FREEZE 1.5 LITRES / NK	4	21.75	87.00
Total Parts :			78,330.20

Steve CLKK)
27/7/22, 2:30pm

OD-M1 NL
Excess-?
PIP
My Policy
30 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



Labour 1	:	53,464.00
Parts	:	78,330.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	9,225.59
Grand Total	:	141,019.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	-
Reported by	Both
Date of Accident	17/07/2022 19:30 (SGT)
Exact Location of Accident	Second Link Bridge, Second Link Expy, Kampung Tiram, 81550 Gelang Patah, Johor, Malaysia
Additional Location Information	towards Tuas
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV1553U
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Wu Pei Kam
NRIC No	SXXXX657B
Email Address	eikawg@yahoo.com
Mobile Phone No	(Phone) +65-96511526
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	216i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DH0M120061622100

DRIVER

Name of Driver	Pui Chuk Kong
NRIC No	SXXXX911Z
Date Of Birth	23/07/1975

Occupation (Draft)
Date Of Driving Pass Indoor
Driving experience 22/08/2007
Gender 14 YEARS AND 11 MONTHS
Mobile Number Male
Alt. Phone Number (Phone) +65-96604632
Email Address *
Address francispui@yahoo.com
Address complement Bk 631 Senja Road #29-222
Postcode *
Is the driver the policyholder? 670631
If No, Relationship of the Driver with the Insured No
Does Driver Own Other Vehicles? Friend
Vehicle Registration Number of Other Vehicle Owned by Driver No
Insurance Company of Other Vehicle Owned by Driver *

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 3
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

PASSENGER 1

Name Wu Pei Kam
Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Car A, SMV 1553U was travelling on Tuas Second Link Bridge towards Singapore custom. However, was unable to stop in time and involved in collision to Car B, SLP 899Y, which was in front of Car A. Car B was subsequently collided to Car C, SJJ 4004S ahead. The accident happened around 1930 hours, 17 July 2022. There was no one reported injured at scene.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP899Y

Vehicle Manufacturer	(Draft)
Vehicle Model	Porsche
Vehicle Variant	Cayenne
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	(Phone) +65-90225082
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJJ4004S
Vehicle Manufacturer	Volvo
Vehicle Model	Xc90
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-96555321
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation**.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

18 JUL 2022

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

18 JUL 2022

Lim Lai Foong

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

SG custom ← SECOND LINK BRIDGE TURS

A C B A


A CMY 1553U
B SEP 899Y
C SJJ 4004S

Describe Circumstance of the Accident


Car A, 8MV1553U was travelling on Tuas Second Link Bridge towards Singapore Custom. However, was ~~not~~ unable to stop in time and involved in ~~rear~~ collision to Car, B, SLP899Y, which was in front of Car A. Car B was subsequently collided to Car C, 3JJ4004S ahead. The accident happened around 1930hrs, 17 July 2022. There was no one reported injured at scene.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

18 JUL 2022


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

18 JUL 2022

Lim Lai Foong

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

