11/30/22, 2:04 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd. Our File No: CS/AIS22007038/KCY3Q2

79 Robinson Road #09-01 Date: 30/11/2022 Singapore 068897

REFERENCE

Insured/Claimant: YUNG MING LIOW Policy No: SP2001878200-01

Date of Loss: 21/07/2022 Nature of Claim: OD Claim No: 202222005760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFA7731B

Make & Model: SEAT ALHAMBRA, 1.4 STYLE 15 (A) Engine No: DFM022543

Reg. Date: 06/07/2017 (Man. Year: 2017) VSSZZZ7NZHV720227 Chassis No:

Colour: Metallic Grey Odometer: 73026 km

Engine Capacity: 1968 cc Market Value/New Car Price: S\$64,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18 Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 6 mm Front Right Side: Goodvear 7 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,516.70	2,856.70	660.00	18.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	800.00	350.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,666.70	3,656.70	1,010.00	21.64
Approved Total (Overridden) (S\$)		2,550.00		
- Excess (S\$)	642.00	600.00	42.00	6.54
(S\$)	4,024.70	1,950.00	2,074.70	51.55
+ GST 7.00/7.00% (S\$)	281.73	136.50	145.23	51.55
Nett Amount (S\$)	4,306.43	2,086.50	2,219.93	51.55

INSPECTION

Date of Assignment: 25/07/2022 Present Location: City Auto Pte Ltd (HQ)

City Auto Pte Ltd (HQ)

27/07/2022 Inspected At: 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Date Inspected:

Singapore 575722

Estimated Period of Repair: 4.0 days

KENNETH KONG CELINE FONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts: M1-SUV SEAT ALHAMBRA 1.4 STYLE 15 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFA7731B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*Rear bumper (WCP)	Buckled	1,725.00 F	*1,725.00 F
2	1	*Rear bumper retainer - RH (WCP)	Distorted	102.00 F	*102.00 F
3	1	*Taillamp - RH (WCP)	Broken	700.00 F	*700.00 F
4	1	*Rear boot lamp - RH (WCP)	Serviceable	600.00 F	*-F
5	1	*Rear bumper reflector - RH (WCP)	Scratched	70.00 F	*70.00 F
F=Fra	anchise part.				
			Sub Total (S\$)	3,197.00	2,597.00
		+ Margin on	319.70	259.70	
			Total Parts (S\$)	3,516.70	2,856.70
		Report was unsubmi	itted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	450.00	400.00		
2	- Spray painting in affected and replace parts	New	700.00	400.00		
	Gross Labour Cost (S\$)		1,150.00	800.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >