

HOCK WAH MOTOR WORKSHOP PTE LTD

011 BEDOK INDUSTRIAL PARK E
 OK NORTH AVE 4,
 -2008/10/12 SINGAPORE 489977
 EL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96418360
 PHUA HONG YEE (PAN HONGYU)
 BLK 16 SIMEI STREET
 11-09
 SINGAPORE 529942
 TEL : FAX :
 PH : 96418360
 ATTN :

ESTIMATE BILL

Number : EB00006041
 Date : 21/07/2022
 Case No : AD00012901
 Vehicle No : SLL9454J
 Chassis: RU11213752
 Year of Mfr 2016
 Policy No 5107531505-03
 Model : HONDA VEZEL 1.5X
 CVT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
31	ANTI-RUST COATING	1.0	350.00	0	350.00
32	WIRING	1.0	40.00	0	40.00
33	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
34	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
35	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	250.00	0	250.00
36	TO REMOVE & REFIT FUEL TANK	1.0	250.00	0	250.00
37	FOUR WHEEL ALIGNMENT	1.0	150.00	0	150.00
Labour 1 Sub Total					5,470.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : ELEVEN THOUSAND FOUR HUNDRED SEVENTY-FOUR AND CENTS SEVENTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		10,724.08
			GST 7.00%		750.69
			TOTAL		11,474.77

Date of accident : 20/07/2022 08:15 AM. Place : AYE EXIT ONTO JALAN BUKIT MERAH junction of lower delta

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

7-3992.1
 202
 3193.68
 240
 2610

6043.68
 202
 4230