

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22007044/AGA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SCX2878J **Insured Vehicle No :** SLA9626M

Date of Loss: 21/07/2022 Nature of Claim: TP Claim No: 6008210286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCX2878J**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045251

Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: WAUZZZF40JA022326

Colour: Black Odometer: 90490 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16

Front Left Side: PETLAS 6 mm Rear Left Side: PETLAS 6 mm

Front Right Side: PETLAS 6 mm Rear Right Side: PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,237.00	0.00	5,237.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,302.00	1,602.00	1,700.00	51.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,539.00	1,602.00	6,937.00	81.24
+ GST 7.00/7.00% (S\$)	597.73	112.14	485.59	81.24
Nett Amount (S\$)	9,136.73	1,714.14	7,422.59	81.24
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,014.14		

INSPECTION

Date of Assignment: 29/07/2022

Date Inspected: 29/07/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,609.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	2		*REAR BUMPER LIGHT REFLECTOR REAR LH/RH	Not Necessary	92.00 FS	*- FS
5	2		*REAR BUMPER SENSOR INNER /OUTER REAR	Not Necessary	265.00 FS	*- FS
6	4		*REAR BUMPER SENSORS SEAL RING	Not Necessary	10.00 FS	*- FS
7	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
8	2		*REAR BUMPER SEAL	Not Necessary	32.00 FS	*- FS
9	1		*PACKING ADHESIVE	Not Necessary	21.00 FS	*- FS
10	1		*AUDI CHROME LOGO	Not Necessary	144.00 FS	*- FS
11	1		*AUDI A4 CHROME EMBLEM	Not Necessary	104.00 FS	*- FS
12	1		*AUDI TFSI CHROME EMBLEM	Not Necessary	104.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	5,237.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	1,700.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,302.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >