

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0624/2022/EQ
DATE : 25-Jul-22
WIP : 34308

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/7/2022.

YOUR INSURED VEH NO : SLA 9626 M

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 15 Sep 22

OWNER'S NAME : MR TAN BOON CHAU
ADDRESS : BLK 8 CHOACHU KANG GROVE
#16-17, SOL ACRES
SINGAPORE 688206
TELEPHONE : HP +65 92956968
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700072771-04
VEHICLE NO : **SCX 2878 J**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC
MODEL YEAR : 01/11/2017
ENGINE NO : CVN 045251
CHASSIS NO : WAUZZZF40JA022326
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Jul-22
PLACE OF ACCIDENT : ALONG BUKIT TMAH ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 2878 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$	500.00
3	TO RESPRAY REAR BUMPER AND REAR LID.	\$	1,700.00	\$	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 3,302.00	\$	1,602.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 2878 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,609.00	
2	REAR BUMPER SPOILER	1	\$ 276.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER LIGHT REFLECTOR REAR LH/ RH	2	\$ 92.00	
5	REAR BUMPER SENSOR INNER / OUTER REAR	2	\$ 265.00	
6	REAR BUMPER SENSORS SEAL RING	4	\$ 10.00	
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	
8	REAR BUMPER SEAL	2	\$ 32.00	
9	PACKING ADHESIVE	1	\$ 21.00	
10	AUDI CHROME LOGO	1	\$ 144.00	
11	AUDI "A4" CHROME EMBLEM	1	\$ 104.00	
12	AUDI "TFSI" CHROME EMBLEM	1	\$ 104.00	
13	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS			: \$ 5,237.00	\$ -
TOTAL LABOUR CHARGES			: \$ 3,302.00	\$ 1,602.00
GRAND TOTAL			: \$ 8,539.00	\$ 1,602.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-06/09/22



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

