Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd To: ERGO Insurance Pte. Ltd.

8 Temasek Boulevard 51 Ubi Ave 1 #01-25 #04-01 Suntec Tower Three Paya Ubi Industrial Park Singapore 038988 Singapore 408933

Attn: Date: 06 Jan 2023 Ivy Yong

Preliminary Advice

Vehicle No : YN9586Y Accident Date : 18/07/2022 Make : MITSUBISHI CANTER Policy No. : DMCG21014266

Assignment Date : 25/07/2022 Excess : S\$500.00 : 6

Date of Inspection : 26/07/2022 Est. Duration of Repair

Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)

BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A

SINGAPORE 768761

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,930.82 (Estimate \$11,435.82 + Supplementary \$495.00)
Revised Amount	:S\$	9,233.97
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,233.97
Lump Sum Repair	:S\$	

Total Loss Consideration

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	12,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,847.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.