

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 26 Jul 2022

Preliminary Advice

Vehicle No	: YN9586Y	Accident Date	: 18/07/2022
Make	: MITSUBISHI CANTER	Policy No.	: DMCG21014266
Assignment Date	: 25/07/2022	Excess	: S\$500.00
Date of Inspection	: 26/07/2022	Est. Duration of Repair	: 6
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,435.82
Revised Amount	:S\$	7,480.22
Check Items (Estimated)	:S\$	3,910.60
Total	:S\$	11,390.82

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 36,000.00
COE / PARF Rebate	:S\$ 12,153.00
Salvage Value	:S\$

Margin for Repair

:S\$ 23,847.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE THE "REWRITE ADVERTISEMENT" IS WITH INSURER POLICY.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.