



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS/ASM22007048/Vqy3m4 Date: 28/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6383A	Veh. Inspected	SLA 555T
Policy No.		Coverage (\$)	0.00
Claim No.	S2M047DM	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	25/07/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY 2.4 A	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	RC11037561	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45R18	YOKOHAMA	5 mm
L/H Front Tyre	235/45R18	YOKOHAMA	5 mm
R/H Rear Tyre	235/45R18	YOKOHAMA	5 mm
L/H Rear Tyre	235/45R18	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/07/2022	Inspection Date	26/07/2022
Survey held at	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE		
Repairer	SPEEDWERKZ PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	