

# SPEEDWERKZ PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9619 5936/ Email: info@speedwerkz.biz

VEHICLE NO: SLA555T

MAKE & MODEL: HONDA ODYSSEY

DOA: 23.07.2022

CLAIM TYPE: TP CLAIM

## ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER	1	\$ 968.70	
REAR BUMPER SIDE RETAINER @ SGD 68.20	2	\$ 136.40	
REAR BUMPER BRACKET @ SGD 61.40	2	\$ 122.80	
REAR TAILGATE	1	\$ 1,159.80	
REAR TAILGATE LOGO	1	\$ 78.20	
REAR TAILGATE GLASS INNER SPONGE SEAL	1	\$ 98.60	
REAR TAILGATE OUTER CHROME GARNISH	1	\$ 226.90	
REAR TAILGATE INNER LOCK	1	\$ 386.70	
REAR TAILGATE WEATHER STRIP	1	\$ 228.60	
REAR TAILGATE SENSOR	1	\$ 296.70	
REAR TAILGATE LAMP @ SGD 596.70	2	\$ 1,193.40	
REAR END PANEL TOP GARNISH TRIM	1	\$ 362.80	
REAR END PANEL	1	\$ 786.40	

\$ 6,046.00

LESS 20% \$ 1,209.20

SUB TOTAL \$ 4,836.80

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
SUNDRIES	1	\$ 50.00	
REAR TAILGATE GLASS SEALANT	1	\$ 45.00	
REAR TAILGATE INNER TRIMBOARD CLIPS	1 SET	\$ 55.00	
REAR END PANEL SEALANT	1	\$ 45.00	
REAR BUMPER CLIPS	1 SET	\$ 50.00	
REAR NUMBER PLATE WITH GARNISH	1	\$ 55.00	
REVERSE SENSOR	1 SET	\$ 280.00	

SUB TOTAL \$ 580.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ALL WIRING AND LIGHTING SYSTEM	1	\$ 80.00	
REMOVE, REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	1	\$ 1,200.00	
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	

TRANSFER TAILGATE ATTACHMENT, TRIMS, GARNISH TO FACILITATE REPAIRS	1	\$ 150.00	
REMOVE AND INSTALL REAR TAILGATE GLASS	1	\$ 150.00	
RE-POSITION, DRILL & ALIGN REVERSE SENSOR	1	\$ 150.00	
TRANSFER REAR COMPARTMENT TRIMS, GARNISH TO FACILITATE REPAIRS	1	\$ 150.00	
CONDUCT WATER SEEPAGE TEST	1	\$ 150.00	
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	

**SUB TOTAL** \$ 3,430.00

**GRAND TOTAL** \$ 8,846.80