

Don Seng Company (SG) Pte Ltd

160 Sin Ming Drive
#04-05
Sin Ming Autocity
5575722

Our client SLX9067E

TP claim against Lompac Insurance (Your insured: GBE8624Y)

Repairer's estimate

Parts

1	Fender clips	10	3	30
2	Bumper retainer	2	80	160
3	Front bumper	1	1450	1,450
4	Bumper clips	10	3	30
5	Front bumper LH black trim	1	250	250
6	Front PDC sensor	2	200	400
7	Front bonnet	1	1640	1,640
8	Bonnet inner heat foam	1	580	580
9	Bonnet hinge	2	190	380
10	Bonnet damper	2	280	560
11	Front grille	1	650	650
12	Lower grille	1	420	420
13	LH front headlight	1	2800	2,800
14	LH front headlight bracket	1	275	275
15	LH front LED fog lamp + garnish	1	850	850
16	19" Sports Rims	1	1200	1,200
17	Front LH Tyre	1	600	600
18	LH Front fender	1	1230	1,230
19	LH Front fender shield	1	290	290
20	LH fender black trim	1	240	240
21	Fender / Bumper trim rivets	20	5	100
22	Front LH lower arm	1	690	690
23	Front LH control arm	1	650	650
24	Front LH wheel bearing	1	540	540
25	Front LH knuckle arm	1	1320	1,320
26	Front LH upper arm	1	750	750
27	Front LH driveshaft	1	1880	1,880
28	Front LH absorber	1	950	950
29	Front steering rack	1	1480	1,480
30	Front LH steering tie rod (mid link)	1	320	320
31	Front LH steering tie rod end	1	365	365
Parts Total:				\$ 23,080.00

Labor

1	Check wiring and system function	1	380	380
2	Rust proofing on affected areas	1	500	500
3	Wheel Alignment before and after repair	1	260	260
4	Programming of new headlight	1	350	350
5	Labor to remove and refit front fender, front bumper, (FRONT LH) lower arm and suspension components, rim and tyre, headlight, bonnet	1	2500	2,500
6	To respray damaged and refitted parts (Front fender, front bumper, bonnet)	1	1200	1,200
Labor Total:				\$ 5,190.00

TOTAL: \$ 28,270.00

Supplementary items would be included if noticed during the course of repair

Contact:

Phone - 92960289

Mr Chai - 96250518

Not Notified

Resurvey B4pam

5 days

L1 Bup @ 4650p

1/kennerth

96910663

Wheel Alignment
repair needed

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: