

*Not Withheld
1/1 Surp &
Recovery After Painting*

4 days

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email: kentsengcarservices@gmail.com

M/s India International Insurance Pte Ltd	DATE	03.08.2022
64 Cecil Street #04,05 IOB Building	CAR NO	SMA 8886 Z
Singapore 049711	MAKE	Subaru Forester

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SNF 8565 J

Pc	Pcs	JFISJ5KC5JG110444	UNIT PRICE	AMOUNT
<u>Recommended Parts</u>				
1	pc	Front bumper	<i>Bu</i>	\$649.70
10	pcs	Front bumper clips	<i>na</i>	\$50.00
1	pc	Front bumper left hand side retainer	<i>DI</i>	\$35.10
1	pc	Front bumper fog lamp garnish (left)	<i>na</i>	\$66.90
1	pc	Front bumper fog lamp chrome (left)	<i>na</i>	\$58.40
1	pc	Front bumper fog lamp (left)	<i>na</i>	\$281.70
1	pc	Front left side fender	<i>na</i>	\$495.80
1	pc	Front left side fender inner cowling	<i>Return</i>	\$135.70
8	pcs	Front left side fender inner cowling clips	<i>na</i>	\$40.00
1	pc	Front left side head lamp	<i>ng cut</i>	\$2,580.40
1	pc	Front left side tyre rim	<i>na</i>	\$765.90
<u>Recommended Labour</u>				
		Straightening, repairing and realigning onto the front affected area, cutting front left side fender, dismantle & replace the above mentioned parts.		\$1,100.00
		To putty and re-spray painting on front bumper, front left side fender & touch up front left side door.		\$800.00
		Rust-proofing on the front accident affected portions.		\$150.00
Total				\$7,209.60

208

*✓
✓
X
X
X
✓
✓
✓
X*

*400
400
300*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved for final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Susan Lim
KENT SENG CAR SERVICES