

ESTIMATE OF REPAIR

Veh# : SJL8762A

Accident Date : 25/7/2022

Location : KALAN BAHAR (JALAN BOON LAY)

Model: TOYOTA COROLLA ALTIS

15/12/2008 14/12/2023

3P: SLS9353E (CHINA TAIPEG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Rehd</i>	571.20	✓	
2	10pcs	Rear bumper clips <i>Rehd</i>		30.00	✓
3	2pcs	Rear bumper screw clips <i>Rehd</i>		20.00	✓
4	1pc	Rear bumper enforcement <i>Rehd</i>	151.40	✓	
5	1pc	Rear bumper sponge <i>Rehd</i>	142.80	✓	
6	2pcs	Rear bumper o/s & n/s reflector <i>Rehd</i>	125.40	✓	
7	2pcs	Rear bumper o/s & n/s retainer <i>Rehd</i>	162.80	✓	70
8	2pcs	Rear reverse sensor <i>Rehd</i>		280.00	210
9	1pc	Rear end panel <i>Rehd</i>	681.90	✓	
10	1pc	Rear end panel inner trim <i>Rehd</i>	253.50	✓	
11	4pcs	Rear end panel inner trim clips <i>Rehd</i>		16.00	✓
12	1pc	Rear spare wheel board cover <i>Rehd</i>	240.20	✓	
13	2pcs	Rear o/s & n/s tail lamp <i>Rehd</i>	878.20	✓	730
14	2pcs	Rear o/s & n/s tail lamp clips <i>Rehd</i>		30.00	✓
15	2pcs	Rear o/s & n/s tail lamp panel <i>Rehd</i>	563.80	✓	
16	2pcs	Rear o/s & n/s tail lamp seal <i>Rehd</i>	40.00	✓	
17	1pc	Rear boot cover <i>Rehd</i>	874.40	✓	
18	1pc	Rear boot cover weatherstrip <i>Rehd</i>	174.40	✓	
19	1pc	Rear boot cover emblem <i>Rehd</i>	71.50	✓	
20	1pc	Rear boot cover 'COROLLA' emblem <i>Rehd</i>	61.70	✓	
21	1pc	Rear boot cover 'ALTIS' emblem <i>Rehd</i>	67.70	✓	
22	1pc	Rear boot cover 'LX' emblem <i>Rehd</i>	51.20	✓	
23	1pc	Rear boot cover inner trim <i>Rehd</i>	282.25	✓	
24	11pcs	Rear boot cover inner trim clips <i>Rehd</i>		33.00	✓
25	2pcs	Rear o/s & n/s boot cover reflector <i>Rehd</i>	710.20	✓	235
26	4pcs	Rear boot cover o/s & n/s stopper <i>Rehd</i>	174.00	✓	
27	2pcs	Rear boot cover o/s & n/s hinges <i>Rehd</i>	264.40	✓	
28	1pc	Rear boot cover moulding chrome <i>Rehd</i>	287.10	✓	
29	4pcs	Rear boot cover moulding clips <i>Rehd</i>		16.00	✓
30	1pc	Rear boot cover lock (Upper) <i>Rehd</i>	291.60	✓	189
31	1pc	Rear boot cover lock (Lower) <i>Rehd</i>	43.10	✓	
Sub Total:			7,164.75	425.00	0.00
			25%	0%	10%
After Less %:			5,373.56	425.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	1,200.00	800	
2		To spray painting.	1,200.00	800	
3		To remove & replace rear reverse sensor	100.00	50	
4		To check wiring.	100.00	30	
5		To re seal anti rust.	100.00	60	
Sub Total:			2,700.00		
Total:			8,498.56		
LKK Auto Consultants charges 20%					6,798.85

LKK Auto Consultants hereby certifies that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Chan San Choon
Director
DipEng. AAE MIMI,MSAE(Aust)



Approved by Repairer

Signature: [Signature]

24 hr accident call

SJL8762A ESTIMATEPg1



TP China. M20532EE106123310

Xiao Tony

4454.50

3340.87

S.N: 276.

Adrian Lg
4/526/07/22

06899

total: 5356.87

2/s: A.2K