

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708415

Date : 26/07/2022
Vehicle Num. : SMD 5652K
Make/Model : TOYOTA HARRIER
Chassis/Eng# :
Accident Date : 25/07/2022
Claim No. :
Reference : 3PTY
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1 PC	LIST ITEMS :			
2.	1 PC	TAILGATE		1816.10	1,827.00
3.	1 PC	TAILGATE HARRIER EMBLEM		62.20	96.00
4.	1 PC	TAILGATE TURBO EMBLEM		98.00	156.00
5.	1 PC	TAILGATE LOCK		604	820.00
6.	1 PC	TAILGATE WEATHERSTRIP TWI		398	547.00
7.	1 PC	TAILGATE TRIM BOARD			774.00
8.	1 PC	TAILGATE GLASS MOULDING			198.00
9.	2 PC	TAILGATE LAMP		686.00	1,372.00
10.	1 PC	REAR BUMPER			773.00
11.	1 PC	REAR BUMPER LOWER GARNISH			480.00
12.	2 PC	REAR BUMPER SIDE RETAINER		94.00	188.00
13.	2 PC	REAR BUMPER REFLECTOR		95.00	190.00
14.	1 PC	REAR BUMPER SPONGE			194.00
15.	1 PC	REAR END PANEL			947.00
16.	1 PC	REAR END PANEL GARNISH			481.00
17.	2 PC	REAR FENDER INNER TRIM		971.00	1,942.00
18.	4 PC	REVERSE SENSOR		432.00	1,728.00
19.	1 PC	REVERSE SENSOR WIRE HARNESS			282.00
20.	4 PC	REVERSE SENSOR BRACKET		54.00	216.00
List TotalS\$:					13,261.00
25.00% Discount S\$:					3,315.25
					9,945.75

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708415

Date : 26/07/2022

Vehicle Num. : SMD 5652K

Make/Model : TOYOTA HARRIER

Chassis/Eng# :

Accident Date : 25/07/2022

Claim No. :

Reference : 3PTY

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1 PC	REAR NUMBER PLATE		45.00 X
2.	1 PC	TAILGATE SEALANT		120.00 <i>SV</i>
3.	12 PC / <i>set</i>	TAILGATE TRIM BOARD CLIPS	5.00	60.00 <i>SV</i>
4.	1 PC	TAILGATE GLASS SEALANT		40.00 <i>SV</i>
5.	1 PC	TAILGATE GLASS INNER SEAL		100.00 <i>SV</i>
6.	12 PC / <i>set</i>	REAR BUMPER CLIP	5.00	60.00 <i>SV</i>
7.	12 PC	REAR BUMPER RIVET	5.00	60.00 X
8.	12 PC	REAR END PANEL GARNISH CLIPS	5.00	60.00 X
9.	20 PC	REAR FENDER INNER TRIM CLIP	5.00	100.00 X
Special Nett Total S\$:				645.00
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING				50.00 <i>20</i>
RESPRAY ANTI RUST				150.00 <i>60</i>
APPLY BODY SEALANT TO CAR JOINTS				150.00 <i>50</i>
TRANSFER TAILGATE PARTS				150.00 <i>60</i>
TRANSFER TAILGATE GLASS				150.00 <i>120</i>
INSTALL REVERSE CAMERA				200.00 <i>SV</i>
INSTALL REVERSE SENSOR				120.00 <i>SV</i>
TO REMOVE INNER TRIM, GARNISH AND ETC TO FACILITATE REPAIRS AND TO FIX BACK				200.00 <i>80</i>

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708415

Date : 26/07/2022

Vehicle Num. : SMD 5652K

Make/Model : TOYOTA HARRIER

Chassis/Eng# :

Accident Date : 25/07/2022

Claim No. :

Reference : 3PTY

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO RECALIBRATE PDC USING DIAGNOSTIC SCANNER	300.00	X
		TO RECALIBRATE AUTO TAILGATE USING DIAGNOSTIC SCANNER	300.00	X
		TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	900.00	600
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	900.00	800
		Labour Total S\$:		3,570.00

E. & O.E.

Total S\$: 14,160.75

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8907
252
6680.25
230
1840
8750.25
202
7000