



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY			Ref: CC4/ASM22007077/Upa3q2 Date: 18/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9380T	Veh. Inspected	SLU 6884Z	
Policy No.	P2465703	Coverage (\$)	0.00	
Claim No.	S2M047DP	Excess (\$)	0.00	
Assign From		Assign Date	26/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2040452A688367	Colour	WHITE	
Odometer	153908 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2022	Inspection Date	26/07/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	