



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207446

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/12/2022
Reference CC6/CTI22007088/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. PC 9116K
Insured Veh. GBH 8775D
Claim No. SNM22D205219/C02
Policy No. DMCVSNW00117762102
Accident Date 08/03/2022
Inspection Date 21/07/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22007088/Apa3q2 Date: 01/12/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 8775D	Veh. Inspected	PC 9116K
	Policy No.	DMCVSNW00117762102	Coverage (\$)	0.00
	Claim No.	SNM22D205219/C02	Excess (\$)	0.00
	Assign From		Assign Date	21/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ V220	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDF44781523539944	Colour	WHITE
	Odometer	50262 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16C	NEXEN	6 mm
	L/H Front Tyre	205/65 R16C	NEXEN	6 mm
	R/H Rear Tyre	205/65 R16C	NEXEN	6 mm
	L/H Rear Tyre	205/65 R16C	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/03/2022	Inspection Date	21/07/2022
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9116K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SLIDING DOOR LH (N)	DISTORTED	2,850.00	2,850.00
1	SLIDING DOOR INNER LOCK L/H(N)	DAMAGED	950.00	480.00
1	SLIDING DOOR OUTER HANDLE INNER GARNISH LH (N)	CRACKED	680.00	240.00
1	SLIDING DOOR AUTO MOTOR L/H (N)	NOT NECESSARY	1,780.00	-
1	SLIDING DOOR HINGE LH (N)	NOT NECESSARY	530.00	-
1	SLIDING DOOR BLACK STICKER L/H (N)	NECESSARY	68.00	68.00
	LESS 10% DISCOUNT		-	-363.80
			6,858.00	3,274.20
	<u>SPECIAL NETT ITEMS</u>			
1	WINDSCREEN GUM (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		400.00	400.00
	SPRAY PAINTING ACCIDENT AFFECTED PARTS.		900.00	700.00
	UNDERCOAT.		100.00	50.00
	REMOVE AND REPLACE SLIDING DOOR AUTO MOTOR AND CALIBRATION.		450.00	80.00
	TO TRANSFER DOOR GLASS AND DOOR FITTINGS.		180.00	100.00
			2,030.00	1,330.00
	GRAND TOTAL		8,928.00	4,644.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CC6/CTI22007088/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 9116K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 9116K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

