

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	BLUWEL AUTOMO	TIVE SERVICE PTE LTD		Ref:	CS/TP22007089/Uvy3m4	
	BLK 1 KAKI BUKIT #01-28/53/55/56 (M 417883	AVE 6 IAIN OFFICE)SINGAPORE		Date:	15/08/2022	
	ON BEHALF OF TA	AN CHIN LAI		Code:	TP149	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.		Veh. Inspected		SJM 9838D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From		Assign Date		26/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA MARK X 250G (A)	c.c		2499	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	GRX1203067814	Colour		BLACK	
	Odometer	150767 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 ZR17	KUMHO		6 mm	
	L/H Front Tyre	215/55 ZR17	KUMHO		6 mm	
	R/H Rear Tyre	215/55 ZR17	KUMHO		6 mm	
	L/H Rear Tyre	215/55 ZR17	KUMHO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/07/2022	Inspection Dat	е	26/07/2022	
	Survey held at	urvey held at BLUWEL AUTOMOTIVE SERVICE PL				
		BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				