

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007100/EVY3M4**Date:** 01/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00071042202

**Claimant Vehicle No :** SLG6388M **Insured Vehicle No :** GBJ6357E

Date of Loss: 20/07/2022 Nature of Claim: TP Claim No: SNM22D205073/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLG6388M**

Make & Model: MAZDA BIANTE, 2.0 SKYACTIV-G SP.6EAT (A) Engine No: PE30915209

Reg. Date: 25/10/2016 (Man. Year: 2016) Chassis No: JM6CC1071G0110012

Colour: White Odometer: 0 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R15 Rear Tyre Size: 205/55 R15

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment: 26/07/2022

Date Inspected: 26/07/2022 Inspected At: ACCORD AUTO SERVICES PTE LTD (BUKIT MERAH)  
BLK 1009 BUKIT MERAH LANE 3, #01-80  
SINGAPORE 159723

Estimated Period of Repair: 0.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$70,000.00
OMV :	\$21,760.00
PARF Rebate (1) :	\$15,724.00
Quota Premium Paid :	\$57,002.00
COE Rebate (2) :	\$24,181.00
Total Rebate (1) + (2) = :	\$39,905.00

The total amount incurred will be Market Value \$70,000.00 minus Total Rebate \$39,905.00 = \$30,095.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2022)
Parts:	M1-MPV	MAZDA BIANTE 2.0 SKYACTIV-G SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG6388M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >