

Your Ref : SNM22D205073/C02

Date: 01<sup>st</sup> Aug 2022

Our Ref : CS/CTI22007100/Evy3m4

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLG 6388M  
INSURED VEHICLE: GBJ 6357E  
ACCIDENT ON 20/07/2022**

Instruction was received to inspect the vehicle Reg. No. SLG 6388M. The inspection was conducted on 26/07/2022 at the premises of M/s Accord Auto Services Pte Ltd, Blk 1009 Bukit Merah Lane 3, #01-80, Singapore 159723.

The following vehicle information was recorded:

Registration Number	: SLG 6388M
Make/Model	: Mazda Bianta Skyactiv-G 2.0 SP.6EAT
Year of Registration	: 2016
Body Colour	: White
Chassis Number	: JM6CC1071G0110012
Engine Capacity	: 1998 cc

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is S\$40,000.00 (Sin Dollars: Forty Thousand only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 70,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 39,905.00)

Nett Liability

S\$ 30,095.00

S\$ 30,095.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 40,000.00

Nett Liability

S\$ 40,000.00

(a) – (b) =

(S\$ 9,905.00)

The amount of estimated saving of S\$9,905.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.