

Not Authorised  
Recovery B4 painting  
\$2411.90

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9739M**

**AAD2206-029**

**25 JUL 2022**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHB9739M**

JTDKB3FU703091359

200303878K

TOYOTA

PRIUS GEN 4

07/06/2022

**PC1315E/CHINA**

28/08/2020

**PART**

- 1 RIM
- 1 LINER, FRONT FENDER, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 COVER, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, RH

**LIST**

|              |           |                 |   |
|--------------|-----------|-----------------|---|
| \$           | Sm        | 1,900.10        | X |
| \$           | DI        | 210.30          | ✓ |
| \$           | B         | 977.80          | ✓ |
| \$           | Bu        | 521.00          | ✓ |
| \$           | DI        | 80.10           | ✓ |
| <b>TOTAL</b> | <b>\$</b> | <b>3,689.30</b> |   |
| <b>25%</b>   | <b>\$</b> | <b>922.33</b>   |   |
|              | <b>\$</b> | <b>2,766.98</b> |   |

**Special Nett**

- 1 TYRE
- 1 FRT BUMPER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

|              |           |               |        |
|--------------|-----------|---------------|--------|
| \$           | Sm        | 350.00        | X      |
| \$           | Sm        | 65.00         | 601.00 |
| \$           | un sm     | 130.00        | +      |
| \$           | nde       | 65.00         | X      |
| <b>TOTAL</b> | <b>\$</b> | <b>610.00</b> |        |

**TOTAL PARTS \$ 2,300.00**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 301

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 X

**Trans-cab Auto Services Pte Ltd****AAD2206-029**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9739M**

Panel Beating, Knocking And Straightening The Necessary  
Portion, Remove And Renewal Of Parts, Adjust And Realign  
The Same

\$ 1,600.00 400/

To transfer of rear end panel fittings, attachment to facilitate  
bodywork repair.

\$ ~ 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 480/

To reinstall rear bumper parking sensor.

\$ ~ 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ ~ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 15/

To check steering geometry and computer wheel alignment

\$ 220.00 60/

To remove and refit of rear fender fittings, attachment and  
perform water seepage test.

\$ ~ 170.00 X

**TOTAL \$ 5,100.00****Over All Total \$ 10,166.98****(PART-BY-PART) Repair Days****20 Days**

2 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: