

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SJS 5896E

TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

Estimate No: ES2290737/YISHUN  
Date: 26 Jul 2022  
Policy No: 5110539659-02  
Veh Reg No: SJS5896E  
Make/Model: TOYOTA TOYOTA  
CAMRY 2.0 AUTO ABS  
AIRBAG  
Chassis No: MR053BK4107047724  
Engine No: 1AZE144553  
Reg. Date: 25/08/2009

WS Ref: TP/AIG  
Claim Type: Third Party  
Accident Date: 24/07/2022  
TP Veh Reg No: GBK7420T

*Not authorized  
11/24 @ 2850h  
Penny Atm Rain  
4 days*

## Estimate Repair Cost to Vehicle No :SJS5896E

| Description                                                        | U/Price  | Quantity | List Price<br>S\$    | Amount<br>S\$ |
|--------------------------------------------------------------------|----------|----------|----------------------|---------------|
| <b>List Price</b>                                                  |          |          |                      |               |
| 1 FRONT BUMPER                                                     | 570.20   | 1 PC     | 570.20               | ✓             |
| 2 FRONT BUMPER RH RETAINER                                         | 95.10    | 1 PC     | 95.10                | ✓             |
| 3 FRONT BUMPER CLIPS                                               | 3.50     | 6 PCS    | 21.00                | ✓             |
| 4 FRONT BUMPER REINFORCEMENT                                       | 443.50   | 1 PC     | 443.50               | ✓             |
| 5 RH HEADLAMP                                                      | 1,150.10 | 1 PC     | 1,150.10             | ✓             |
| 6 FRONT BUMPER RH FOG LAMP                                         | 283.50   | 1 PC     | 283.50               | ✓             |
| 7 FRONT BUMPER RH FOG LAMP GARNISH                                 | 100.60   | 1 PC     | 100.60               | ✓             |
| 8 WINDSCREEN WASHER TANK                                           | 218.40   | 1 PC     | 218.40               | ✓             |
| 9 FRONT RH FENDER                                                  | 793.20   | 1 PC     | 793.20               | ✓             |
| 10 FRONT RH FENDER INNER SHIELD                                    | 155.70   | 1 PC     | 155.70               | ✓             |
| 11 FRONT RH FENDER INNER SHIELD CLIPS                              | 3.50     | 6 PCS    | 21.00                | ✓             |
| 12 FRONT RH FENDER EMBLEM (VVTI)                                   | 45.20    | 1 PC     | 45.20                | ✓             |
| 13 ENGINE UNDER COVER LH                                           | 198.80   | 1 PC     | 198.80               | ✓             |
|                                                                    |          |          | 4,096.30             |               |
|                                                                    | Less 25% |          | 1,024.08             | 3,072.23      |
| <b>Labour</b>                                                      |          |          |                      |               |
| 14 PANEL BEATING,REPAIR FRT SUPPORT PANEL,RH FENDER<br>INNER PANEL | 600.00   | 1 LA     | 600.00               | 500           |
| 15 PUTTY & RESPRAY PAINT (PEARL WHITE)                             | 700.00   | 1 LA     | 700.00               | 550           |
| 16 RUSTPROOFING                                                    | 30.00    | 1 LA     | 30.00                | ✓             |
|                                                                    |          |          | 1,330.00             | 1,330.00      |
|                                                                    |          |          | Total                | S\$ 4,402.23  |
|                                                                    |          |          | Add GST @ 7%         | 308.16        |
|                                                                    |          |          | Total Amount Payable | S\$ 4,710.39  |

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE