

TP Ergo
Cedline.

SDU1733D. 2016 March.

Chevrolet Orlando. 1362 cc

KL1YA7589GK333166

Rear Bumper Upper	} Distal	1330 ✓
Rear Bumper Lower		493 ✓
Rear Bumper Sill Plate (silver)	Missing	223 ✓
Rear Bumper Clips.	new	50 (800) 30 (500)
Rear Bumper Side Holder x 02	MP	118 x 2 = 236. x
Rear Bumper Step Plate	Missing	166. ✓
Rear Bumper Reflector x 02	RH and	140 x 2 = 280 140
Rear Bumper Brake Lamp.	Assembled	307. ✓
Rear Bumper Centre Guide.	Assembled	148. ✓
Rear Bumper Side Guide x 02	MP	112 x 2 = 224. x
Rear Bumper Reinforcement.	Perforated	863 ✓
Rear Bumper Sensor x 04.	2 pieces damaged	215 x 4 = 860 430
Rear Bumper Sensor Seal x 04.	new	15 x 4 = 60 ✓
Rear Bumper Sensor Wire Harness.	MP new	291 x

SDU1733 D.

Rear End Panel	Dented	776. ✓
Rear End Panel Top Garnish	Rehind	186 ✓
Rear End Panel Top Garnish Clips.	Per	20(SN) ✓
Rear End Panel Sealant.	Per	60(SN) ✓
Taillamp x02	RH and	468 x 2 = 936. ⁴⁶⁸
Tailgate	Dented	1528 ✓
Tailgate Lock	Dmg	331 ✓
Tailgate Weatherstripe.	Lt	272 ✓
Tailgate Reflector x02	RH cut	328 x 2 = 656 ³²⁸
Tailgate Inner Trim Board.	Crushed	311 ✓
Tailgate Inner Trim Board Clips	Per	30(SN) ✓
Chevrolet Wording.	} Per	133 ✓
Orlando Wording		108. ✓
LS Wording		45 ✓
Turbo Emblem.		151 ✓
Tailgate Glass Sealant.	Per	60(SN) ✓

SPU 1733 D.

	Rear RH Fender Inner Trim Board	incl 78/	✓
	Rear RH Fender Inner Trim Board Clips.	per 30/sn)	✓
	Spere Tyre Panel Tool BOX.	Del 418	✓
	Spere Tyre Panel Top Cover	MP 284	+
9996			
899640	Rear Camera	incl MP 680/sn)	X
S.N: 230	Panel Beating.	1400	800
	Spray Painting.	1200	800
	Wiring	50	30
	To remove cruise sensor	100	50
	To remove car camera.	100	50
	To spray tail coat	2100	1500
	To remove upholstery.	1500	600
	To transfer tailgate fittings.	150	80
	To remove tailgate g/ass	1800	1200
	To remove video recorder	100	50

total: 11326.40
9K
4/51
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

9,000