

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22007115/TNY3Q2**Date:** 19/12/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJN1183G**Insured Vehicle No :** YP6126B

Date of Loss: 24/07/2022

Nature of Claim: TP

Claim No: CDMCG22001486

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJN1183G**

Make & Model: HYUNDAI AVANTE, 1.6 SR (A)

Engine No: G4FC8U554045

Reg. Date: 04/02/2009 (Man. Year: 2008)

Chassis No: KMH DU41BR9U634762

Colour: Beige

Odometer: 168308 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: APLUS 6 mm

Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm

Rear Right Side: APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,216.96	2,006.80	210.16	9.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	830.00	400.00	32.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,446.96	2,836.80	610.16	17.70
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	3,446.96	2,250.00	1,196.96	34.73
+ GST 7.00/7.00% (S\$)	241.29	157.50	83.79	34.73
Nett Amount (S\$)	3,688.25	2,407.50	1,280.75	34.73

INSPECTION

Date of Assignment: 26/07/2022

Date Inspected: 27/07/2022 Inspected At:

Em-1 Auto Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate Sector C, #01-68

Singapore 575643

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2022)
Parts:	143	HYUNDAI AVANTE 1.6 SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1183G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,112.70 FL	*1,021.30 FL
2	1		*BONNET INNER RUBBER	Necessary	46.20 FL	*46.20 FL
3	1		*SET BONNET INSULATOR CLIPS	Necessary	30.00 FL	*30.00 FL
4	1		*BONNET INNER LOCK	Not Necessary	76.20 FL	*- FL
5	2		*BONNET STOPPER	Not Necessary	36.00 FL	*- FL
6	1		*HEADLAMP LH	Cracked	486.30 FL	*486.30 FL
7	1		*FRONT BUMPER	Deformed	470.80 FL	*470.80 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
9	1		*FRONT GRILLE	Cracked	380.50 FL	*365.00 FL
10	1		*FRONT GRILLE BADGE	Necessary	52.50 FL	*38.90 FL
11	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,771.20	2,508.50
- List Item Discount on L Items 20.00/20.00% (\$)	554.24	501.70
Total Parts (\$)	2,216.96	2,006.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$)			1,230.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >