

Vehicle Damage Assessment Report for [SJN1183G]

Estimate Created: 01/12/2022 15:25 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 01/12/2022 15:30 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Avante
Engine Type			
License Plate Number	SJN1183G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$2250.00 with 3 days for repair

Insurlogic 1 (01/12/2022 15:30)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
BONNET		1	1021.30	-20.00 %	817.04
BONNET INNER RUBBER		1	46.20	-20.00 %	36.96
BONNET INSULATOR CLIPS		1	30.00	-20.00 %	24.00
HEADLAMP LH		1	486.30	-20.00 %	389.04
FRONT BUMPER		1	470.80	-20.00 %	376.64
FRONT BUMPER CLIPS		1	30.00	-20.00 %	24.00
FRONT GRILLE		1	365.00	-20.00 %	292.00
FRONT GRILLE BADGE		1	38.90	-20.00 %	31.12
FRONT GRILLE CLIPS		1	20.00	-20.00 %	16.00

Parts Subtotal 2,006.80

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	300.00	0.00 %	300.00
CHECK WIRE	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREA	Full spray	500.00	0.00 %	500.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 330.00

Paint Labor Subtotal 500.00

Labor Subtotal 830.00

Summary

Repair Cost 2,836.80

Discount(21 %) (586.80)

2,250.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 2,250.00