

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

300 #17- 1. Insi Pol Cla Ass 2. Mal Eng Cha Odd Bra	NPAC INSURAN BEACH ROAD -04/07 THE CO ured Veh. licy No.	NCOURSESINGAPORE 199555	- (THIRD PARTY CLAIM	CS3/LPC22007119/Tvy3 26/07/2022 LPC2	
#17- 1. Insi Pol Cla Ass 2. Mal Eng Cha Odd Bra	ured Veh.	NCOURSESINGAPORE 199555 Policy Particulars :	Code:	LPC2	
1. Instance Pol Cla Ass 2. Eng Cha Odd Bra	ured Veh. licy No.	Policy Particulars :	- (THIRD PARTY CLAIM		
Instance Instance Instance Pol Cla Ass 2.	licy No.	<u> </u>	- (THIRD PARTY CLAIM		
Instance Instance Instance Pol Cla Ass 2.	licy No.	<u> </u>	<u>,</u> T		
Pol Cla Ass 2. Mal Eng Cha Odd	licy No.	GBE 9357L	Vala la anastad	SDD 8328J	
Cla Ass 2. Mal Eng Cha Odd Bra			Veh. Inspected		
Ass 2. Mal Eng Cha Odd Bra	im No.		Coverage (\$)	0.00	
2. Male Eng Cha Odd Bra			Excess (\$)	0.00	
Mal Eng Cha Odd Bra	sign From	GERALD POH	Assign Date	26/07/2022	
Eng Cha Odd Bra	2. Vehicle Particulars & Condition				
Cha Odd Bra	ke & Model		c.c	0	
Odd Bra	gine No.	HIDDEN	Year of Reg.		
Bra	assis No.		Colour		
	Odometer - Steering				
Car	akes		Modification		
Gei	neral				
3. Conditions of Tyres					
		Size	Make	Balance	
R/H	H Front Tyre			mm	
L/H	I Front Tyre			mm	
R/H	l Rear Tyre			mm	
L/H	l Rear Tyre			mm	
4.	Description of Damages				
5.	General Information				
Acc	cident Date	14/07/2022	Inspection Date	27/07/2022	
Sur	rvey held at	S9 BUILDING 55 SERANGOON	NORTH AVE 4, #02-10		
	Repairer	1 STOP GARAGE PTE. LTD.			
5a.	5a. Remarks				
B) T THE	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				