



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2302851
3 ANSON ROAD #16-00	INV Date	08/05/2023
SPRINGLEAF TOWER	Reference	CC6/CTI22007124/Dpa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SHD 6846X
Insured Veh.	GBG 8988L
Claim No.	SNM22D205224/C02
Policy No.	DMCVSNA00145442103
Accident Date	26/07/2022
Inspection Date	27/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI22007124/Dpa3q2

Date: 08/05/2023

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8988L	Veh. Inspected	SHD 6846X
Policy No.	DMCVSNA00145442103	Coverage (\$)	0.00
Claim No.	SNM22D205224/C02	Excess (\$)	0.00
Assign From		Assign Date	27/07/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHC851CVLU194637	Colour	BLUE
Odometer	143516 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	5 mm
L/H Front Tyre	195/65 R15	DUNLOP	5 mm
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/07/2022	Inspection Date	27/07/2022
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6846X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	481.10	-
1	FRONT BUMPER REINFORCEMENT ABSORBER (RH)	NOT NECESSARY	186.50	-
1	FRONT BUMPER MOULDING CENTRE UPPER	NOT NECESSARY	368.50	-
1	FRONT BUMPER MOULDING	NOT NECESSARY	93.60	-
1	FRONT BUMPER BRACKET TOP (RH)	NOT NECESSARY	35.00	-
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	28.00	-
1	FRONT BUMPER RETAINER MOUNTING (RH)	NOT NECESSARY	65.30	-
10	FRONT BUMPER CLIPS	NOT NECESSARY	25.00	-
1	FRONT BUMPER GRILLE (RH)	NOT NECESSARY	186.90	-
1	FRONT BUMPER AIR DUCT (RH)	NOT NECESSARY	153.80	-
1	DAY LIGHT, RH	NOT NECESSARY	642.50	-
1	HEADLAMP SUPPORT PANEL ASSY	NOT NECESSARY	1,139.30	-
1	HEADLAMP (RH)	NOT NECESSARY	3,987.30	-
1	FRT PILLAR UPPER COVER - OUTER (RH)	NOT NECESSARY	89.60	-
1	FRONT FENDER (RH)	BUCKLED	490.70	490.70
1	FRONT FENDER APRON PANEL SIDE SUPPORT (RH)	NOT NECESSARY	238.80	-
1	FRONT FENDER APRON PANEL (RH)	NOT NECESSARY	756.20	-
1	FRONT FENDER APRON PANEL UPPER (RH)	NOT NECESSARY	329.00	-
1	FRONT FENDER SHIELD (RH)	TORN	164.70	164.70
1	FRT DOOR (RH)	BUCKLED	1,797.20	1,797.20
1	FRT DOOR RUBBER	NECESSARY	250.00	250.00
1	FRONT DOOR REGULATOR (RH)	NOT NECESSARY	750.40	-
1	FRONT DOOR POWER MOTOR, RH	NOT NECESSARY	689.20	-
1	FRONT DOOR HINGE UPPER (RH)	NOT NECESSARY	165.76	-
1	FRONT DOOR HINGE LOWER (RH)	NOT NECESSARY	153.70	-
1	FRONT DOOR CHECK (RH)	NOT NECESSARY	72.98	-
1	FRONT DOOR INNER LOCK (RH)	NOT NECESSARY	385.60	-
1	FRONT DOOR OUTER HANDLE (RH)	CUT / BROKEN	234.80	234.80
1	FRONT DOOR MIRROR ASSY (RH)	BROKEN	1,691.70	1,691.70
1	FRONT DOOR PROTECTOR (RH)	NECESSARY	186.20	186.20

Report Ref No. CC6/CTI22007124/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR OUTER MOULDING (RH)	NOT NECESSARY	110.10	-
1	ROCKER PANEL OUTER GARNISH	MTG CRACKED	715.60	715.60
1	FRONT WINDSCREEN MOULDING	NECESSARY	157.30	157.30
1	FRONT WINDSCREEN PILLAR OUTER (RH)	DENTED	3,764.90	3,764.90
1	WIPER CONTAINER ASSY	NOT NECESSARY	385.40	-
1	FRONT WHEEL RIM (RH)	DISTORTED	1,124.20	1,124.20
1	FRONT WHEEL HUB ASSY (RH)	DAMAGED	678.50	678.50
1	FRONT WHEEL HUB CAP	CUT	346.40	346.40
1	FRONT SHOCK ABSORBER (ASSY) (RH)	DISTORTED	372.50	372.50
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	372.50	-
1	FRONT DRIVE SHAFT (RH)	NOT NECESSARY	1,136.70	-
1	FRONT DRIVE SHAFT EXTENSION RH	NOT NECESSARY	1,125.80	-
1	RACK & PINION ASSY	NOT NECESSARY	2,387.40	-
1	STG TIE ROD	NOT NECESSARY	125.60	-
1	STG TIE END	NOT NECESSARY	94.70	-
1	STABILIZER BAR	NOT NECESSARY	326.80	-
1	STABILIZER BAR LINK	NOT NECESSARY	92.10	-
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	596.80	596.80
1	KNUCKLE ARM (RH)	DISTORTED	663.60	663.60
	LESS 20% DISCOUNT		-6,083.25	-2,647.02
			24,332.99	10,588.08
1	EMBLEM-BLUE DRIVE (RH)	BENT	26.60	26.60
	LESS 20% DISCOUNT		-	-5.32
			26.60	21.28
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT TYRE (RH) (SN)	SERVICEABLE	216.00	-
			337.00	121.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		2,200.00	700.00
	SPRAY PAINTING CHARGE.		2,000.00	700.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT.		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE / REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	REMOVE / REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	REMOVE / REFIX FRONT WINDSCREEN GLASS.		120.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			6,170.00	1,940.00
	GRAND TOTAL		30,866.59	12,670.36
	RECOMMENDED COST OF REPAIRS			12,670.36

Report Ref No. CC6/CTI22007124/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6846X

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6846X

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6846X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

