



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301327

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/03/2023
Reference CC6/CTI22007126/Eya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 2330P
Insured Veh. SLZ 2991Y
Claim No. SNM22D205008/C02
Policy No. DMPCSNW00151272100
Accident Date 16/07/2022
Inspection Date 27/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22007126/Eya3q2 Date: 07/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLZ 2991Y	Veh. Inspected	SKQ 2330P	
Policy No.	DMPCSNW00151272100	Coverage (\$)	0.00	
Claim No.	SNM22D205008/C02	Excess (\$)	0.00	
Assign From		Assign Date	27/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZ16ZEM058827	Colour	BLACK	
Odometer	104049 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	GOODYEAR	4 mm	
L/H Front Tyre	195/55 R16	GOODYEAR	4 mm	
R/H Rear Tyre	195/55 R16	GOODYEAR	4 mm	
L/H Rear Tyre	195/55 R16	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/07/2022	Inspection Date	27/07/2022	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 2330P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	1,600.19	1,147.00
2	REAR BUMPER SIDE RETAINER LH/RH @\$280.71	NOT NECESSARY	561.42	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	1,100.71	-
1	REAR BUMPER LOWER GARNISH	CUT	1,108.60	511.00
1	REAR BOOT EMBLEM	NECESSARY	238.60	97.00
1	REAR BOOT LOGO (JETTA)	NECESSARY	189.77	72.00
1	REAR BOOT LOGO (TSI)	NECESSARY	189.77	54.00
1	REAR TAIL LAMP LH	NOT NECESSARY	500.75	-
	LESS 10% DISCOUNT		-548.98	-188.10
			4,940.83	1,692.90
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPR CLIPS @\$5.00 (SN)	NECESSARY	50.00	30.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			250.00	230.00
<u>LABOUR</u>				
	REMOVE ,REFIT ,REPAIR AND REPLACE ACCIDENT AFFECTED PARTS.		800.00	250.00
	SPRAY PAINT (REAR BUMPER ,REAR BOOT ,REAR END PANEL).		800.00	400.00
	REMOVE AND REPLACE REAR REVERSE SENSOR .		80.00	30.00
	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL.		100.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,810.00	740.00
GRAND TOTAL			7,000.83	2,662.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00
---	--	--	-----------------

Report Ref No. CC6/CTI22007126/Eya3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 2330P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 2330P

RE-INSPECTION

